

FEB 2 2 1996

COMMISSION

Approved by Jeila County

Ĺ	_and Survey	Remonumen	tation
	Peer Group	Under Act 34	5 Of
4	Of 1990 On	1/12	100

LAND CORNER RECORDATION CERTIFICAT

ر	A DE 1990 On 1/1/2	<u>ڪ</u> 199
TE .	Jot Rehana	lino
70	acting hairman	/
4.0	//	

Fo	or corners in	Filing Requi	rement of Act	74, Mich. P.A. 19	970 ^Æ	cting	Chairman	ı /		
	DELTA	Located In:	Corner C	ode ##		•				
	(County)						•			
1	Public Land Survey	T <u>38 N R 24 W</u>	E-8 6	Dana	orded	an.	18 1	996		
١.	Fublic Land Survey	T R				ano	·			
		T R		at 9:	o'clock	M in Lib	er <i>&_</i> _P	age_//	7	
		T R			Alan C.	. T. C.	Reg	. of Dee	de .	
2.	Property Controlling S _	T R		Delta	County, Mic	higan		.01000	us.	
	in Section S _	R								
3.		T R		Register o	f Deeds	Stamp &	File N	umbe)r	
	Property in Sec. S _	T R								
	Lot No, Record				A	в с р	E F G	н і	ј к	L
5.	Private Claims	i] E-9 [NW COR S.28]				5	$\bot \downarrow \bot$	_ 1	-2	_
	E-0 [MI) 4 CON 3.21	ij m-y jaw con s.zoj			3			Ĭ		
					4					
	M.P. DAVIS	field survey on8EPTE	MRER	19 95	5	ĺ	Til	Ĭ	ĺ	ľ
do	hereby certify that under requirement	ents of P.A. 74, Michigan P.A	of 1970, the corn	erpoints mentioned	6 _ 1					
in	lines 1 and 2 above were in confo	rmance with regulations a	nd rules therefor	e as required in the		8	16-1-	-15	14 	13-
cu	rrent manual of survey instructions	of the United States Depa	rtment of the Inte	rior, Bureau of Land	7		 			
Ma	anagement or by a decree of a Court ove were in conformance with the re	of Law and/or that the com	of Land Surveyor	s or by a Decree of a	81	9 20-	-21-	-22	-23	24- I
Co	ourt of Law; established, re-estat	olished, monumented, re-	monumented, re	covered, found as	9	-	 	+		
	pressed below:				103	029	- 2 ['] B -	-27	-26	<u>2</u> 5-
NO	OTE: Not more than 4 corners	, all in the same town a	nd range, may	be recorded	11					\vdash
	on this certificate.				123	132	33-	_34	-35	36-
					13				\perp	
4 14	E-9 [NW COR S.28] WOOD POST - G M.S.NcNABB-1920 - STAKE FOU					'4°W-34 L'	INKS)			
	Description of comer evidenc E-8 [W1/4 COR S.21] NO CORNER E BETWEEN SECTION CORNERS N & 5.0 FEET WEST OF A DIRECT L N-S WOODS ROAD.	VIDENCE OR MONUMENT FOUL S AND IN LINE WITH ANC	ND. REESTABLISHE LENT N-S FARM FE	D CORNER POSITION NCE LINE, WHICH PL	AT MIDPOINT ACE THE 1/4	••	TE OI	F MI	CHI	C
٠	E-9 [NW COR S.28] FOUND IN PLA TO THE NORTH. NO EVIDENCE OF WELL WITH THE RECORDS OF MCI AS TO THE POSITION OF THE OF	F NCNABB'S COR FENCE POS NABB. ACCEPTED EXISTING	T BT FOUND. DIS	TANCE SOUTH TO 1/4	COR CHECKS	4	LAND	M. P. AVIS SURVI NO. 16926		35/
^	Description of monument for o	corner and accessories	established to	pernetuate locating	the position	on of the	corner:	****		
	•				2o poorti					
ì	E-8 SET BERNTSEN A1NB30 ALUMN MO SOFT MAPLE 8" HEMLOCK 13			CORNER PUSITION. URVEY MONUMENT SIG	N DUGA					
	N24°W S81°E		BUAR O'S S54'W	NORTH NORTH	n IVOI					
	9.12' 40.55'		33.82'	2.36' (TO FAC	E)					
	.5120 30033	4133		MIJU ĮIU INU	~,					
F	2-9 SET, OVER EXISTING MONUMENT, COR FENCE POST POWER	POLE SURVEY MONUM	31/4" ALUMN CA ENT SIGN POST	STAMPED TO ID THE		ION				

N37°W 42.92' (TO FACE)

N49°E 45.40' (TO FACE)

8.1

\$30°E 28.85' (TO FACE)

\$38°W 36.91' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE

8 PAGE 117

Surveyor's Michigan License No.