1577 A 1786

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta	County
Land Survey Remonit	Mentation
Meer Group Under A	ct 345 Of
PA-O(1990 On 3-3	ر 199 مـــــــ
12 00 D	00 10

Fo	r corners in	Chairman		
	DELTA	Located In:	Corner Code ##	
	(County)			RECEIRGE Mar 4 1999
1.	Public Land Survey	T <u>39 N R 18 W</u> T <u>39 N R 18 W</u> T R T R	F - 5 F - 7	9:00 per AM 150
2.	Property Controlling in Section	S T R S T R		Call Carnet of got a lately
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

In a field survey on FEBRUARY 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

F-5 [N1/4 COR SEC 16] F-7 [N1/4 COR SEC 21]

__ , Recorded Plat _

Lot No.

Private Claims __

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - F-5 [N1/4 COR SEC. 16] A.MERRYWEATHER, DS-1848-SET WOOD POST (IRONWOOD 06" N53°W 22 LINKS) (BEECH 10" S20°E 25 LINKS)
 T.O'BRIEN-1980-SET RR SPIKE IN C/L OF E-W COUNTY ROAD & IN LINE WITH FENCES N-S (PP S73°W 96.2') (ANCHOR BOLT IN FENCE COR N4°E 32.5')
 - F-7 [N1/4 COR SEC 21] A.MERRYWEATHER, DS-1848-SET WOOD POST-(CEDAR 16° S54°W 17 LINKS)(CEDAR 12° N75°E 25 LINKS)
 T.O'BRIEN, RLS-1980-L.2 PG.406 LCR'S-FD IRON SPIKE (FENCE N & S) PP S11°W 41.1' FENCE POST N6°W 32.1'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - F-5 [N1/4 COR SEC. 16] FOUND IN PLACE, IN APPROX C/L OF E-W COUNTY ROAD AND IN LINE WITH FARM FENCES N-S A RR SPIKE. ID CORNER MONUMENT FROM BT'S REC'D AT 1.2 OF LCR'S PG 406. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.
 - F-7 [N1/4 COR SEC 21] FOUND IN PLACE A 8" IRON SPIKE. ID CORNER MONUMENT FROM BT'S RECORDED IN L.2 OF LCR'S PG.406. CORNER MONUMENT FALLS ON APPROX C/L OF E-W COUNTY ROAD AND IN LINES WITH ANCIENT OCCUPATION LINES N. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - F-5 REPLACED EXISTING MON W/A 5/8" X 18" REBAR W/A 31/4" ALUM CAP STAMPED TO 1D THE COR POSITION & RAISED TO GRADE W/A MCM BOX.

5/8* X 18" REBAR W/A 2" ALUM WIT CAP CEDAR 05" ASH 05" SURVEY MONUMENT SIGN POST N45°E S45°E S63°W N57°W SOUTH 25.00' 26.54' 69.79' 59.81' 30.80' (TO FACE)

F-7 REPLACED EXISTING MONUMENT W/A 5/8' X 18" REBAR W/A 31/4" ALUM CAP STAMPED TO ID THE CORNER POSITION.

ASH 06" ASE 05" POWER POLE SURVEY MONUMENT SIGN POST N14°W N62°E S16°W NORTH 26.70' 46.55' 41.25' 17.56' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

LIBER 0009 PAGE 150

Signed by M.R. JAUIS
Surveyor's Michigan License No. 16926

Date 2/15/49