JAM 3 2000

Approved By Delta County Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 1992

SECTION		CORNER RECOR g Requirement of A			leig CI	nairman	-7			
For corners in	. rand	y requirement of i	1	1370	/		1			
DELTA (County)	Located In:	Corner Code #								
1. Public Land Survey	T 39 N R T 39 N R T R			r san	<u>2:00</u> 3:00	este	$_{ m uc}$ P^{j}	И		
Property Controlling in Section Miscellaneous Property in Sec.	S TR_ S TR_ S TR_			· '.	Register of Deeds Stamp & File Number					
L-09	[N1/4 COR SEC 25] L-	-11 [N1/4 COR SEC 36	5]				· ·			
4. Lot No, Recor	ded Plat			а в	CDE	F G	н І	J	K L :	
5. Private Claims				1						
				3	1	- 4 -				
M.P. DAVIS	in a field survey on	NOVEMBER 19	do hereby state that und	er 4 - 7		_ _	_10_	_ 11	12-	
requirements of P.A. 74, Michiga	an P.A. of 1970, the corne	r points mentioned in lin	es 1 and 2 above were	in _						
conformance with regulations and United States Department of the I	Interior, Bureau of Land Ma	anagement or by a decre-	e of a Court of Law and /	ne or 6 18	- 17	_16	_15 -	 14	 13	
that the corner points mentioned Board of Land Surveyors or by	in lines 3, 4 and 5 above v	were in conformance with	n the rules of the Michiga	an _					ļļ	
recovered, found as expressed be			,	8 -19		21	22	<u></u> 2 3	24-	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				9					+	
on this certificate.	-,			10 30	29	-2 ⁸	<u>_2</u> 7	26	25-	
,			•	11			-		+	
		·		12 31	32-	33	-34	35 	36	
NO RECORD EVIDENCE OF -11 [N1/4 COR SEC 36] A.ME M.S.McNABB-1946-SET IR	RRYWEATHER D.S1848	-WOOD POST (HEMLOCK	25" N35°E 15 LINKS)(SUGAR 16"	s41°w 15	LINKS)				
B. Description of corner evid -09 [N1/4 COR SEC 25] NO CO ON LINE WITH SECTION CO EAST WEST FARM DITCH AN AND IN POOR REPAIR. -11 [N1/4 COR SEC 36] FOUND	ORNER EVIDENCE FOUND. ORNERS 1/2 MILE EAST O IN APPROXIMATE LIN	REESTABLISHED CORN AND WEST. CORNER PO E WITH ANCIENT EAST JUNCTION OF FARM F	ER POSITION AT MIDP SITION FALLS ON NOR WEST FARM FENCE DO ENCES WEST AND SOUT	CINT AND TH SIDE OF WWN AND	15	€i	M. P. DAVI: 0 SURV	Ş	GTZ	
BOLT, IDENTIFIED EXISTI WHICH IS STILL GREEN WI BEST AVAILABLE EVIDENCE	TH THE IRON MARKS ST	ILL PLAIN. ACCEPTED	EXISTING MONUMENT	AS BEING TH	HE .	STERE	16926	o sur		
C. Description of monument	for corner and accesso	ories established to pe	erpetuate locating the	position of t	he corner:					
-09 SET A BERNTSEN A1NB30	ALUM MONUMENT WITH T	HE CAP STAMPED TO I	THE CORNER POSITI	ON.						
ASH 4" N31°W 16.38′	N38 [*] E 41.52'	s62°W. 17.42′	SURVEY MONUMENT SIG NORTH 2.10'(TO FACE)							
	NUMENT, A BERNISEN A1 ALSAM 08" W.PINE NO2"W 73.22'	NB30 ALUM MONUMENT 48"(OLD BT) SUR N64°E 74.32'	WITH THE CAP STAMPE VEY MONUMENT SIGN F NORTH 1.18'(TO FACE)	ED TO ID THE POST	E CORNER PO	NOITIR	•			
NOTE: BEARINGS TO REFERENCE	,	-DISTANCES ARE TO A			•	NLESS O	THERWIS	SE NOT	ED.	
Signed by M.P. L	mui		Date	12/00	199					

Surveyor's Michigan License No.__