SURVEY & TEMONUMENTATION

OCT 2 6 1995

COMMISSION

Approved бу Бена County Land Survey Remonumentation

Peer Group Under Act 345 Of

	1 4.01 1990 Un zeine 6, 1995
LAND CORNER RECORDATION CERTIFIC	ATE PAIO SELO O
LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 1	1970 Adula Chairman
ining troquirement of Act 14, then 12.	or o coo con eg Chairman

١٠ ١٠	Comers in			
	DELTA (County)	Located In:	Corner Code =##	•
1.	Public Land Survey	T <u>+0 -x</u> R _{19 ¥} T R T R T R	_F-7-(F-9)	Recorded 1 M 3 1995
	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R		Walter C. Zhom Reg. of Deeds. Dalta County, Michigan Register of Deeds Stamp & File Number
		Recorded Plat		A 8 C D E F G H + J K L !
in li curr Mar abo Cou	nes 1 and 2 above were rent manual of survey inst lagement or by a decree of ve were in conformance w	in a field survey on	nd rules therefore as required in tment of the Interior, Bureau of Li er points mentioned in lines 3, 4 ar of Land Surveyors or by a Decree	the and 7 18 17 16 15 14 13 14 13 14 15 14 15 16 15 16 15 16 15 16 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16
NO	TE: Not more than 4 on this certificate	corners, all in the same town a e.	nd range, may be recorded	11 12 31 32 33 34 35 36
A.	Description of original	monument and accessories an	d/or subsequent restoration:	· · · · · · · · · · · · · · · · · · ·

F-7 [N1/4 COR SEC. 21] A.MERRYWEATHER, D.S. - 1848 - WOOD POST (WILLOW 06"-NORTH-08 LINKS) (SPRUCE 06"-S50"E-06 LINKS)

F-9 [S1/4 COR SEC. 21] A.MERRYWEATHER, D.S. - 1848 - WOOD POST (OAK 07"-N48" E-09 LINKS) (W.PINE 24"-S70" W-90 LINKS)

D.A.BORTHERTON-1910-ID CORNER POSITION FROM STUMP OF GLO OAK BT 4 REMAINS OF W.PINE BT-SET NEW STAKE NO WIT'S NOTED

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVEWRY OR MONUMENTATION

- F-7 [N1/4 COR SEC. 21] RESTORED CORNER POSITION AT MIDPOINT BETWEEN SECTION CORNERS EAST AND WEST NO EVIDENCE OF ORIGINAL CORNER OR ACCESSORIES FOUND.
- F-9 [S1/4 COR SEC. 21] FOUND IN PLACE A 1" IRON PIPE. IDENTIFIED SAME FROM THE SUPERVISOR'S PLAT NO. 1 OF NAHMA TOWNSHIP AS RECORDED IN LIBER "B" OF PLATS ON PAGES 82 & 83. NO OTHER EVIDENCE FOUND. ACCEPTED EXISTING MONUMENT AS THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSTION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - F-7 SET BERNTSEN AIMB30 ALUMN MON. W/A 3-1/4" CAP STAMPED TO ID THE CORNER POSITION. CEDAR 08* TAMRACK 04" CEDAR 04° CEDAR 06" SURVEY MONUMENT SIGN POST S50°E ¥47° € N65'W 530,8 MORPH 22.53' 21.981 10.85 28.291 2.83' (TO FACE)
 - F-9 SET, OVER EXISTING MONUMENT, A BERNTSEN ALNB30 ALUMN MON. W/A 3-1/4" CAP STAMPED TO ID THE CORNER POSITION.

MAPLE 12" NOTE: CORNER POSITION IS LOCATED IN RESIDENTIAL MAPLE 10" MAPLE 15" \$87°W S87°E S15°W YARD NO SIGN POST SET.

29.301 2.10 6.60

Surveyor's Michigan License No. 16926

NOTE:	BEARINGS	70	REFERENCE	OBJECTS	ARE	MAGNETIC	-DISTANCES	ARE	TO NAIL	W/A	DELTA	COUNTY	REFERENCE	TAG.	UNLESS	OTHERWISE NOT	PED.

M.D. Harris Signed by __