FEB 1 8 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On Law 20, 1994
1 Well Behinelin
/ / New Electrical

Peer Group Under Act 345	Of
P.A. Of 1990 On Jan 20, 1	99 <u>4</u>
1 NeW Sehme	
Octing Chairman	
/	5

Fo	r corners in DELTA			
	(County)	Located In:	Corner Code =##	
1.	Public Land Survey	T 40 N R 22 W T R T R T R		Recorded January 21, 1994 st9:00 o'clock m. in Liber Page 352
2.	Property Controlling	S T R		When c. Thus Reg. of Doesis.
_	in Section	S T R		Desta County, faichigan
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
		Recorded Plat		A B C D E F G H I J K L M
	[C-3] NW COR SEC 8	[D-3] N1/4 COR SEC 8		2 6 5 4 3 2 1 1 2 3 4 7 3 4 7 3 9 10 11 12 12
١, .			<u> </u>	
in	lines 1 and 2 above were	in conformance with regulations	A. of 1970, the corner points mentio and rules therefore as required in artment of the Interior, Bureau of L	the 17 16 15 14 13
Ma	anagement or by a decree of	f a Court of Law and/or that the cor	ner points mentioned in lines 3, 4 ar	nd 5 8 19 20 21 22 23 24
Co	ourt of Law; established,	-	d of Land Surveyors or by a Decree e-monumented, recovered, found	as ⁹
ex	pressed below:			10 30 29 28 27 26 25
NO	OTE: Not more than 4 on this certificate	corners, all in the same town e.	and range, may be recorded	11 12 -31 -32 -33 -34 -35 -36
A.	Description of original	monument and accessories a	and/or subsequent restoration:	

C-3 [NW COR SEC 8] WOOD FOST - A. MERRYWEATHER, D.S. - 1848 (W.PINE 28"-S25"W-99 LINKS) (W.PINE 26"-N39"E-86 LINKS)

D-3 [N1/4 COR SEC 8] WOOD POST - A. MERRYWEATHER, D.S. - 1848 (N.FINE 14"-S12°E-1.06 CHS) (N.PINE 28"-WEST-2.25 CHS)

1885 SURVEY RECORDS OF C.E. BROTHERTON INDICATES "CORNER IN PLACE" NO NEW WIT'S NOTED OR OTHER COMMENTS MADE IN HIS NOTES

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1932 M.S. McNABB FOUND IRON STAKE IN PLACE AT FENCE CORNER

NO RECORD EVIDENCE OF SUBSEQUENT PERPETUATION OF THIS CORNER

- C-3 [NW COR SEC 8] FOUND AN IRON PIPE AT THE JCT OF FENCE LINES EAST & SOUTH DISTANCES WEST ALONG THE SEC LINE TO THE COUNTY ROAD (NOW STATE HWY.) & TO OTHER COR'S COMPARES WELL WITH OTHER RECORD DISTANCES - ACCEPTED THIS MONUMENT AS A CAREFUL & FAITHFUL REESTABLISHMENT OF OF THE POSITION OF THE ORIGINAL CORNER.
- D-3 [N1/4 COR SEC 8] FIELD INVESTIGATION REVEALED NO EVIDENCE OF THE ORIGINAL COR OR OF ANY SUBSEQUENT WORK TO ESTABLISH THE COR - ESTABLISHED NEW CORNER POSITION ON LINE BETWEEN SEC COR'S E & W AND AT 'GLO" DISTANCE WEST OF A WELL DEFINED MARSH EDGE, THIS POSITION IS VERY NEAR THE MIDPOINT BETWEEN SEC CORNERS.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - C-3 REPLACED EXISTING MONUMENT W/A 4" X 4" X 36" CONCRETE MONUMENT W/A BRASS CAP STAMPED TO ID THE CORNER POSITION THIS CORNER POSITION IS SURROUNDED BY NOTHING BUT SCRUB BRUSH - NO VIABLE WIT'S NEAR SURVEY MONUMENT SIGN POST - \$45'E - 1.38' (TO FACE)
 - D-3 SET BERNTSEN AIMB30 ALUMN MON WITH THE CAP STAMPED TO ID THE CORNER POSITION.

JACK PINE 8" JACK PINE 10" JACK PINE 11* SURVEY MONUMENT SIGN POST N72°E S40°E \$71°₩ N45°W 0.87' (TO FACE) 30.891 6.381 37.85

Surveyor's Michigan License No. _

Date 11/15/93