## SURVEY & REMONUMENTATION

SEP 1 8 1997

4. Lot No. ...

5. Private Claims \_

## COMMISSION

\_ , Recorded Plat .

A-01 [NW COR SEC 6]

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County
Land Survey Remonumentation
Peer Group Under, Act 345 Of

		·
Located In:	Corner Code ##	880Hdsd 28 July 1997
T40 N R23 V	8-01 & B-01	at 9:00 o'clock a.m.  Liker 8 Fage 205
T R T R		Wallace C. Thomas Data Councy, Mi Hag, of Greds
S T R S T R		
S T R		Register of Deeds Stamp & File Number
	T40 N R23 W T40 N R24 W T R T R S T R S T R	T40 N R23 W A-01 & B-01 T40 N R24 W M-01 T R T R S T R S T R

M-01 SAME CORNER AS A-01 M.P. DAVIS 1997 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

B-01 [N1/4 COR SEC 6]

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

12

- Description of original monument and accessories and/or subsequent restoration: A-01 [NW COR SEC 6] JOHN BURT,D.S. - 1846 (FIR 6"-S06°W-23 LINKS) (TAMERAC 10"-S75°W-15 LINKS)(W.PINE 10"-S18'E-18 LINKS) 1946 RECORDS OF M.S.McNABB INDICATE COR IN PLACE 66' WEST OF SE COR OF SEC 32 T41N R23W, NO DESCRIP, ON MON GIVEN OR BT'S NOTED.
- B-01 [N1/4 COR SEC 6] WOOD POST NOT SET IN ORIGINALS M.S.McNabb - 1946 - ID BY IRON BOLT IN PLACE, 713' WEST OF S1/4 COR SEC 33 T41N R23W-NBT'S ELM 5" S20'E 27.5' ELM 8" N73'E 16.8'
- B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:
- A-01 [NW COR SEC 6] NO CORNER EVIDENCE FOUND. AS PER THE RECORDS OF M.S.McNabe RESET CORNER 66.0' WEST OF THE SE COR OF SEC 32 T41N R23W & ON LINE WITH SAID SE COR & THE S1/4 COR OF SAID SEC 32. ACCEPTED AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.
- B-01 [N1/4 COR SEC 6] UNABLE TO LOCATE IRON BOLT MENTIONED IN McMABB'S NOTES. ID CORNER POSITION BY BOTH OF McNABB'S ELM BTS (NOW DOWN & BADLY DETERIORATED). CORNER POSITION FALLS ON 4TH CORRECTION LINE & 713' WEST OF THE \$1/4 COR OF SEC 33 141M R23W.



W.PII N20	NE 09" W. 0'W	N50°E	RUCE 06" S S89°₩	ITION E COR SEC 32 T411 EAST 66.0'	N R23W .
B-01 SET A SPRUCE S84°W 28.62	7 * E	AR W/A 3 <sup>1/4</sup> " ALUM LM 06" S1/4 08°E 1.11'		ITION	

11010	BUULLINGS	10	VAL REPUBLICATION OF CLA	UM	EAGUATIO	DIGITARCOD. ARE	TO UNDER U	MELBINERCE	- au	CHILD	- カチはでが装すりで	101
			A A			Sitt .			*			
		,	MP Douis					M	last	(22		
Signer	thv		MIN LAHONS			•••	214 7 4 5	Date 🕖	23/	9/		

Surveyor's Michigan License No. 16926