FEB 1 8 1994

For corners in

Land Survey Remonumentation Peer Group Under Act 345 Of P.A. Of 1990 On April 60, 199 4

Approved By Delta County

LΑ COMMISSION Fili

	(_	Men	Delin	elur
ND CORNER RECORDATION CERTIFICA	ATE	acting	Chairman	; l
ing Requirement of Act 74, Mich. P.A. 19	970	/		

7-377

	DELTA	Located In:	Corner Code ##	
	(County)	Located III.	Comer Code ++	
1.	Public Land Survey	T <u>40 N R 23 W</u> T <u> </u>	C-9 6 C-10	Recorded January 21, 1994
	Property Controlling in Section	S T R S T R		Death County, Michigan
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
5 do in cu Ma ab Co	Private Claims C-9 [NW COR SEC 2 hereby certify that under relines 1 and 2 above were irrent manual of survey instrangement or by a decree of ove were in conformance wi	recorded Plat	of 1970, the corner points mention of rules therefore as required in timent of the interior, Bureau of Ler points mentioned in lines 3, 4 are of Land Surveyors or by a Decree	ned the 6 18 17 16 15 14 13 and 7 and 5 8 19 20 21 22 23 24 of a
NC	OTE: Not more than 4 or on this certificate.	corners, all in the same town a	nd range, may be recorded	12 3 3 3 3 3 3 3 3 3 5 3 6
Α.	C-9 [NW COR SEC 29] W	monument and accessories and icod Post - A. Merryweather, D. 19 - 1895 - Stake In Place- No New	S 1846 (BLACK ASH 5"-N75°E	-3 LINKS) (CEDAR 6°-N70°W-15 LINKS)

- M.S. McNABB -1914 SURVEY FOR ROAD COMMISSIONER RESET IRON PIN WHERE STAKE STOOD BEFORE ROAD GRADING (MAIL BOX POST-S28 W-29.6') (CEDAR STUMP-N19'17'E-65.4')
- M.S. McNABB 1920 IRON PIN FROM PREVIOUS SURVEY REFERENCE MONUMENT NW 33'
- C-10 [W1/4 COR SEC 29] WOOD POST A. MERRYWEATHER, D.S. 1846 (MAPLE 6"-N33"E-19 LINKS) (MAPLE 24"-S40"W-28 LINKS) M.S. McNABB - 1914 - FOUND WOOD STAKE IN HWY- REPLACED SAME WITH IRON STAKE (SW COR SCHOOL LOT N88°10'E-27.5")
  - M.S. McNABB 1924 IRON STAKE FROM PREVIOUS SURVEY SW COR NEW SCHOOL BLDG NELY 95.6
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - C-9 [NW COR SEC 29] IRON PIN BY MCNABB APPARENTLY DESTROYED IN ROAD CONSTRUCTION, FOUND HIS REF-ERENCE MONUMENT (NW 33') BROKEN & IN POOR CONDITION, STRAIGHTENED AS BEST COULD BE DONE AND RESET CORNER POSITION FROM THE REFERENCE MONUMENT. ACCEPTED AS BEING A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.
  - C-10 [W1/4 COR SEC 29] McNABB'S IRON PIN APPARENTLY DESTROYED IN ROAD CONSTRUCTION, RESET CORNER POSITION BY RETRACEMENT OF MCNABB'S 1924 SURVEY OF THE WEST LINE OF SEC 29 - IDENTIFIED NW & SW COR'S OF SEC 29 & PLACED 1/4 COR IN LINE WITH FENCE LINE EAST AND 2.3' EAST OF A STRAIGHT LINE BETWEEN COR'S. PER THE RECORDS OF MCNABB, SCHOOL HOUSE AS REFERENCED BY MCNABB NOW APPEARS TO HAVE BEEN CONVERTED TO A RESIDENTIAL HOME THE SW COR OF WRICH BEARS N40°E 95.9' FROM THE 1/4 COR AS ESTABLISHED, RECORDED AS 95.6'. ACCEPTED THIS POSITION AS BEING A CARE-FUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. C-9 SET, INSIDE A MON BOX, A 5/8' X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION

ANCHOR POLE POWER POLE POWER POLE SURVEY MONUMENT SIGN POST N44°W N57°E \$48°W S41°E 46.30' (TO FACE) 46.30' (TO FACE) 44.40' (TO FACE) 43.23' (TO FACE)

C-10 SET A 5/8" X 18" REBAR W/A 2" ALUMN CAP STAMPED TO ID THE CORNER POSITION

POWER POLE TELE POLE SW COR HOUSE NOTE: THIS SECTION OF THE COUNTY ROAD IS PROME TO FROST HEAVE \$42°W EAST N40°E THEREFORE I HAVE ELECTED NOT TO PLACE A MON BOX AT 38,901 37.901 95.91 THIS POSITION

NOTE: BEARINGS TO REFERENCE OBJECTS ARE NAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS OTHERWISE NOTED 1001

Signed by /// Land	Date	12/29/93
Surveyor's Michigan License No. 16926		ransa tannaura ny sa