SECTION

For corners in

4. Lot No.

5. Private Claims

recovered, found as expressed below:

Approved By Delta County

Land Survey Remonumentation
Peer Group Under Act 345 of
A Of 1990 On Jaly 12, 2001
Robert & himeling
acting Chairman


LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

DELTA (County)	Located In:	Corner Code #	
1. Public Land Survey	T <u>40 N</u> R T <u>40 N</u> R T <u>R</u> T R		RECORDED 28 July 2000 AT 9:00 O'CLOCK a.m.
Property Controlling in Section	SR		LIBER 9 PAGE 229
3. Miscellaneous Property in Sec.	S		DELTA COUNTY MI REG. OF DEEDS
	S TR_ B-07 [N1/4 COR	R SEC 19] J-12 [C1/4 COR SEC 35	Register of Deeds Stamp & File Number

in a field survey on M.P. DAVIS JUNE 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

_, Recorded Plat



- A. Description of original monument and accessories and/or subsequent restoration:
- B-07 [N1/4 COR SEC 19] ALGERNON MERRYWEATHER, D.S.-1846-WOOD POST-(SPRUCE 08" S70°E 16 LINKS)(SPRUCE 08" N38 W 14 LINKS)
 M.S.McNABB-1921-ORIGINALS GONE-SET PROPORTIONATE BETWEEN CORNERS-SET CEDAR STAKE, NO WIT'S NOTED.
- J-12 [C1/4 COR SEC 35] NOT SET IN ORIGINALS
 D.A.BROTHERETON-1905-SET AT INTERSECTION OF 1/4 LINES-NO WIT'S NOTED M.S.McNABB-1925-IRON STAKE AT FENCE POST-NO WIT'S NOTED.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- B-07 [N1/4 COR SEC 19] FOUND IN PLACE THE POINTED REMAINS OF A WOOD POST. ID SAME AS THAT SET BY McNABB IN 1925 FROM HIS DISTANCE EAST FROM THE NE CORNER OF SEC 19 AND EXISTING OCCUPATION (FENCE LINE EAST AND SOUTH). ACCEPTED EXISTING MONUMENT AS BEING A CAREFUL AND FAITHFUL REESTABLISHEMENT OF THE POSITION OF THE ORIGINAL CORNER.
- J-12 [C1/4 COR SEC 35] FOUND IN PLACE, AT A FENCE POST, A 1" IRON PIN. DISTANCES TO ADJOINING 1/4 CORNERS N, S AND W CHECK WELL WITH THE RECORDS OF BROTHERTON AND MCNABB. MON AS FOUND IS 4.70' WEST OF DIRECT LINE BETWEEN N & S 1/4 COR'S. A CHECK OF THE E-W ALIGNMENT WAS NOT MADE AS THE E1/4 COR NOW FALLS IN THE BACK WATER OF A DAM ON THE ESCANABA RIVER. ACCEPTED THE EXISTING MONUMENT AS BEING A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE CORNER POSITION.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 8-07 REPLACED THE POST POINT W/A BERNTSEN A1NB30 ALUM MON WITH THE CAP STAMPED TO ID THE CORNER POSITION. TAMARACK 07" TAMARACK 09" CEDAR 08" TAMARACK 06"

NAR U

N28 E 28.05

S65 E 13.77' \$34 W

28.80

J-12 SET, OVER EXISTING MOUMENT, A BERNTSEN A1NB30 ALUM MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.
RED PINE 12" MAPLE 28" W. CHERRY 05" STEEL WITNESS POST

RED PINE 12" N78°W 54.504

53.74

42.624

STEEL WITNESS POST NORTH

1.29'(TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

Date

Surveyor's Michigan License No.