SUHVEY & REMONUMENTATION

OCT 03 2000

Approved By Delta County

4.0

	_,
and Survey	Remonumentation
	Under Act 345 of
I SOLCHULD	Unioni Act 343 di

	_	·	۳	18	*	λÉ
ಾ	<u> </u>	C	ğ	11	,)	W.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

A_O(199	00pfe	ly 12,20 d	0
This	Shin	<u>ly 12,20 c</u> elin o	
1. Vila			

For corners in				activ	9 Chairma	111	Y	-
DELTA (County)	Located In:	Corner Code #		ŕ				
1. Public Land Survey	T <u>40 NR</u> T <u>40 NR</u> TR TR			RECORD AT9	00 0'CLO	uly 20	000 .m.	
2. Property Controlling	S TR_			LIBER_		GE <u>Z</u>	<u>/'/</u>	
in Section	S TR_			سبسبي بالأسيب	Bu C. 2		*	
Miscellaneous Property in Sec.	S !R_			DELTAC	OUNTY MI RE	G. OF DE	EDS	
Property at Sec.	1-06 (C1/4 COR SEC 13)	L-09 [N1/4 COR SEC 25]		Register	of Deeds S	tamp &	File N	umber
I, M.P. DAVIS requirements of P.A. 74, Mich conformance with regulations a	, in a field survey on _ igan P.A. of 1970, the comer and rules therefore as required	MAY 00 do hereb r points mentioned in lines 1 and in the current manual of survey is anagement or by a decree of a Co	y state that under	A B C 1	D E F	G H 3	I J	K L
that the corner points mention	ed in lines 3, 4 and 5 above w	vere in conformance with the rule Law; established, re-establishe	s of the Michigan	7	1,—16—	15	1	
recovered, found as expressed	below;	Law; established, re-establishe	d, monumented,	8 19	20 21	22	23	7,
NOTE: Not more than 2 co	amon all in the name town							
on this certificate.	mers, ann the same town	and range, may be recorded		10 30	29 28-			7
							26	725
			•	11	32 33	34	75	
			•	12 31-1		34	35	36-
A. Description of original n	nonument and accessorie	s and/or subsequent restorat	tion:	13	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			A
-06 [C1/4 COR SEC 13] NOT	SET IN ORIGINALS							
M.S.McNABB-1944-FOUND	IRON PIPE IN PLACE AT	INTERSECTION OF 1/4 LINES	. PINE STUMP 18"	' \$55°W 564	POPPLE 6"	N60'E 3	56.8 <i>′</i>	

ESCANABA RIVER.

L-09 [N1/4 COR SEC 25] A.MERRYWEATHER, D.S.-1846 - WOOD POST (CEDAR 06" N39"W 15 LINKS)(CEDAR 12" SO8"E 8.5 LINKS)
D.A.BROTHERTON - 1895- ORIGINALS GONE SET 1/2 DISTANCE BETWEEN CORNERS TELE POLE \$45"E 31' TELE POLE N20"E 56'
M.S.MCNABB-1925-CORNER FALLS IN BACK WATER OF DAM
R.E.SCHMELING-1959-L.3 OF LCR'S PG 73- REESTABLISHED COR FROM RECORDS OF MCNABB-SET AN IRON PIPE W/A BRASS CAP STAMPED TO ID THE
CORNER POSITION. SCHMELING'S ACCESSORIES HAVE ALL BEEN DESTROYED DURING RECONSTRUCTION OF COUNTY ROAD 420 BRIDGE OVER THE

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- L-06 [C1/4 COR SEC 13] FOUND IN PLACE A 1-1/2" IRON PIPE. ID SAME AS THAT BEING FOUND IN PLACE IN 1944 BY McNABB FROM HIS PINE STUMP BT WHICH IS STILL IN PLACE AND BADLY DETERIORATED. ACCEPTED EXISTING MONUMENT AS BEING A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE CORNER POSITION.
- L-09 [N1/4 COR SEC 25] FOUND IN PLACE AND NEAR THE MIDPOINT BETWEEN SEC CORNERS 1/2 MILE E & W SCHMELING'S IRON PIPE W/A BRASS CAP. ACCEPTED EXISTING MONUMENT AS BEING A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

47.16

L-06 SET, OVER EXISTING MONUMENT, A BERNTSEN A1NB3D ALUM MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION MAPLE 14" SURVEY MONUMENT SIGN POST N55°E N35°W S39°E S45°W WEST

L-09 DID NOT DISTURB EXISTING MONUMENT

C/L GUARD RAIL POSTS N44°W N64°E

64.461

C/L COUNTY ROAD 420

SURVEY MONUMENT SIGN POST

\$55°E

35.97

02.954 05.22 22.007

41.054

NORTH

1.32'(TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

Signed by M. A. DAEZI	Date 7/13/00
Surveyor's Michigan License No. 16926	

1.81'(TO FACE)