SURVEY & REMONUMENTATION

JAN 1 4 1998

LAND CORNER RECORDATION CERTIFICATE

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On <u>/ 2- //8'</u> , 199 <u>/</u>

² .A. Of 1990	On <u>/ کلا // لا</u>	, 199 <u>./</u>
000	000	1.
row	8 Sch	neung
activo	Chairman	

For o	corners in SECTION	ON Filing Requir	rement of Act 74, Mich. F	P.A. 1970	acting	Chairma	a <		_
	DELTA	Located In:	Corner Code ##	Source Contract	Dec	19 19	97		
1. 1	Public Land Survey	T 40N R24W T 40N R25W T R	<u>A-7</u> 6 B-7	10 S	8 Pm	a AM			
i 3. I	Property Controlling In Section Miscellaneous Property in Sec.	T R S T R S T R S T R		Z# (1300	Register of Deeds Stamp & File Number				
		ecorded Plat			A B C I	D E F (3 H I	JK	ı N
5. I	Private Claims	-(SAME AS N-7) B-7 [1/4	COR COMMON TO SEC'S 18/19]	2	6-5		_3_	_2_	_1_
in lin curre Mana abov Cour	ereby certify that under request 1 and 2 above were in the manual of survey instrugement or by a decree of a were in conformance with the flaw; established, researched.	in a field survey onNOVEMB; purements of P.A. 74, Michigan P.A. conformance with regulations as actions of the United States Depart Court of Law and/or that the corner the rules of the Michigan Board e-established, monumented, re-	of 1970, the corner points mening rules therefore as required the the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decre	in the f Land 7, and 5 are of a 9 nd as	18 17	7 16 21 21 21 21 21 21 21 21 21 21 21 21 21	15	-1'1 -14 -23	13
•	essed below: E: Not more than 4 coon this certificate.	orners, all in the same town a	nd range, may be recorded	10 11 1 <u>2</u> 13	31 31	2/8	34	35	-25
A-7	INW COR SEC 19] WOOD P H. MILLEN D.S. 1852 (C M.P. DAVIS 1976-IDENTI (BALSAM 9*-S10°W-16.8 [1/4 COR COMMON TO SEC	monument and accessories an 10ST - J. MULLETT D.S. 1848 (CI EDAR 18"-N19'E-16 LINKS){CEDAI FIED MULLETT'S GLO CEDARS-SET FEET) L'S 18/19] WOOD POST - H. MILLI QUARED POST (SPRUCE 10"-S68"E-	EDAR 10"-N53°W-18 LINKS)(CEI R 10"-87 1/2°E-31 LINKS) 3/4" X 18" IRON PIPE (BALSA EN D.S. 1852 (CEDAR 8"-N81°W	DAR 15"-884°W- AM 6"-N64°W-15 J-20 LINKS)(CE	.4 FEET)	°E-32 LIN	S)		
A-7	Description of corner engine COR SEC 19] FOUND ACCEPTED EXISTING MONU ORIGINAL CORNER.	vidence found and/or method THIS DATE DAVIS 1976 IRON PIPE MENT AS BEING A CAREFUL AND FA	applied in restoring or rees E - BOTH BALSAM WITHESSES DE NITHFUL PERPETUATION OF THE	tablishing cor CAD & DOWN. POSITION OF T		E OF M. DA	MIC) P. VIS	Y.C.A.	
6-1	NOW A CLEAR CUT ACCEPT	'S 18/19] FOUND DAVIS 1976 WOO ED EXISTING MONUMENT AS BEING ON OF THE ORIGINAL CORNER.			REGISTRA	LAND SI		R S	A. A.
	REPLACED IRON PIPE WIT. BALSAM 8° CEDAR 6°	S2'W S76°E							
B-7	SPRUCE SNAG 15° BAL S68°E S4	7°₩ N79°E	MENT W/A 3 1/4" CAP STAMPED MONUMENT SIGN POST NORTH 1.94' TO FACE	TO IDENTIFY	THE CORNER	POSITION.			
NOTE	E: BEARINGS TO REFERENCE	E OBJECTS ARE MAGNETIC AND DIS	TANCES ARE TO A NAIL W/A RE	FERENCE TAG U	LESS OTHER	WISE NOTE	D.		