

JUL 06 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County	
Land Survey Remonumentation	
Peer Group Under Act 345 Of	
P.A. Ol 1990 On May 5, 199	ৰ্ফ
May Blownelin	ď
Chairman	4

For corners in					1						
Delta		Locat	ed In:	Corner Code #							
(County)											
1. Public Land Survey		T <u>41N</u> T	N R <u>18W</u> R R	<u>K-9</u>			10.	, 10	.00		
		Ť	 R		ļ	Records	13 N	lay 19	198		
2. Property Controlling	S	_ T	R			at 9:00	o'clock	AM in L	iber 9	Page	81
in Section	S	_ T	_ R			20h	ller c	. ZZ.		Den of	Dande
3. Miscellaneous	S	_ <u>T</u>	_ R				unty, Mic		·	Neg. OI	nacas.
Property in Sec.	s	_ т	_ R	<u> </u>			•	~	· 0	=== N.	
4. Lot No, Re	corded	Plat				Kegi	ster of D	eeas Si	camp &	FILE N	umbei
5. Private Claims					-						
						1 A B	C D	E F G	HI	J 1	K L
						2 6	5	4	-3-	ģ	- 1-
				5 . 65 46		3				_	
I, <u>GERALD W. CARLSON</u> do hereby state that under re						4 - 7 -	8	9	10	—ı [:] 1—	12-
mentioned in lines 1 and 2 a						5					
required in the current manual						618-	17	16	15	1 4	13-
Bureau of Land Management	•				•	7					
mentioned in lines 3, 4 and 5 Land Surveyors or by a Dec				_		8 19-		21		 23	24-
recovered, found as expressed				,		ر ا					
NOTE - Not along them O .		II 2 43				1030-		28-	27	—26—	25-
NOTE: Not more than 2 c on this certificate.	orners, a	iii in the s	same town a	nd range, may be recorde	2 a					-20	
on and conditionte.						11					

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

4" Spruce

A. Description of original monument and accessories and/or subsequent restoration:

1848: A. Merryweather original subdivision survey notes describe the corner monument

K-9:1998: No original corner evidence found. The North-South location of the corner was re-established equidistant between the found Northwest corner of Section 24 and the re-established Southwest corner of Section 25. The East-West location of the corner was proportioned between the "over creek" Call 23.59 chains West and the found Southeast corner of Section 24. The distances North and South are 5270.52' and the distance East is 5286.52'.

N 75°W 20 L

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9: 1998: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet marked Delta County Survey Monument and stamped to identify the corner. Established references to painted blazes and dh nails in:

Cedar

S 57°E 43.27

K-9: Corner common to Sections 23, 24, 25 and 26.

S50°E

as 1/4 post (no corner monument description given) referenced by:

16 L

9" Cedar S 02°E 28.79

11" Cedar

4"Spruce

N 72°W 30.38'

8" Cedar

N 14°W 56.64

Green steel fence post w/ Yellow Survey Marker sign N 87°E 2.00'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.



ROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

24589 Surveyor's Michigan License No.