SURVEY & REMONUMENTATION

JUL 06 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich P A 1970

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
PA OL 1990 On May 5 , 1998
(Must himeling
Chairman

	Filing Require	ement of Act 74, Mich. P.A. 1	1970 Culling Lameting	-
For corners in			Chairman	
Delta	Located In:	Corner Code #		
(County)				
4 D. I. C.	T 44N D 4007			
Public Land Survey	T <u>41N</u> R <u>18W</u> T R	<u>L-9</u>		
	T R		Recorded 13 May 1998	
	T R			~
2. Property Controlling S	TR		a9:00 o'clock AM in Lines 9 Page 85	
in Section S	T R		Walter & Thomas Ros of Dec	d:
3. Miscellaneous S	TR		Delta County, Michigan	
Property in Sec. S	T R		Register of Deeds Stamp & File Numb	o e
4. Lot No, Record	led Plat			_
5. Private Claims			·	
			A B C D E F G H I J K 1	L T
			2 6 5 4 3 - 2	1
CEDALD W. CARLSON	: <i>E</i> :-!-!	. F-h 25 42 00	3	ļ
l, <u>GERALD W. CARLSON</u> , in a field survey on <u>February 25</u> , 19 <u>98</u> , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner			4 7 8 9 10 11 1	12
				L
points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States				 -3-
Department of the Interior, Burea	au of Land Management or	by a decree of a Court of Law	7	Ĺ
and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance			8 19 20 21 22 23 2	4
with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		9		
established, re-established, monu	mented, recovered, tound a	as expressed below:	10 30 29 28 27 26 2	Ĺ.
NOTE: Not more than 2 corner	re all in the same town and	I range may be recorded		!
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		range, may be recorded	11 32 32 34 35	
A. Description of original monu		or subsequent restoration:	13	
-9: South Quarter Corner Section		a deparibe the server		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

6" Balsam

monument as a 1/4 post (no corner monument description given) referenced by:

L-9:1998: No original corner evidence found. The corner was re-established equidistant and on line between the re-established Southwest corner of Section 24 and the found Southeast corner of Section 24. The Distances East and West are 2643.26'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9: 1998: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Delta County Survey Monument stamped to identify the corner. Monument is 0.3' above ground among balsams and scattered hardwoods. Established references using painted blazes and dh nails in:

8" Triple Maple

N 45°W 5.68'

N 42°E 21 L

7" Twin Maple

N 12°E 27.52'

S 34°W 12 L

7" Maple S 48°E 10,11'

8" Maple

S 15°W 31.68

Green steel fence post w/ Yellow Survey Marker sign S 76°W, 2.0'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.



igned by <u>Juall W Caller</u>

Date 4-30-98

Surveyor's Michigan License No. 24589

ORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975