NOV 2 5 1998

For corners in

4. Lot No.

5. Private Claims

DELTA

1. Public Land Survey

2. Property Controlling

Approved by Beita County Land Survey Remonumentation Peer Group Under Act 345 Of

P.A. Of 1990 On Actifle 29, 1998

## LAND CORNER RECORDATION CERTIFICATE SECTION

\_ , Recorded Plat .

C-04 [W1/4 COR S.8] C-05 [NW S. 17]

Filing Require	ment of Act 74, Mich.	P.A. 1970
ocated In:	Corner Code ##	
T <u>41 N</u> R 22 W T R T R	C-04 & C-05	Recurred 16 Nov 1998  at 9:00 stock A.M  Liber 9 Page 105
T R		Walley C. Thous

Delta County, MI Reg. of Deeds

in Section Miscellaneous S Register of Deeds Stamp & File Number Property in Sec.

	•	
, M.P. DAVIS , in a field survey on	JULY 1	. 19 98 .
do hereby certify that under requirements of P.A. 74, Mich		
in lines 1 and 2 above were in conformance with regul	lations and rules th	erefore as required in the
current manual of survey instructions of the United Stat	tes Department of th	ne Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that	the corner points m	entioned in lines 3, 4 and 5
above were in conformance with the rules of the Michiga	an Board of Land Su	rveyors or by a Decree of a
Court of Law; established, re-established, monumer	nted, re-monument	ed, recovered, found as
expressed below:		

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11 12
- Description of original monument and accessories and/or subsequent restoration:
- C-04 [W1/4 COR SEC 8] A.MERRYWEATHER, DS 1847 WOOD POST (BURNT HEMLOCK 10"-N40"E-10 LINKS)(BURNT HEMLOCK 07"-S15"W-22 LINKS) M.S.McNabb-1927-NO CORNER EVIDENCE FOUND. ESTABLISHED CORNER 1/2 DISTANCE BETWEEN CORNERS TAMARACK STUMP 08" S32"E 7.0'
- C-05 [NW COR SEC 17] A.MERRYWEATHER, DS 1847 WOOD POST (BURNT HEMLOCK 12"-N80"E-12 LINKS)(BURNT HEMLOCK 09"-S65"W-17 LINKS) M.S.McNABB-1922-FOUND STAKE IN PLACE, NO EVIDENCE OF ORIGINALS. CEDAR 6" S60°E 13' BALSAM 03" S45°W 10'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-04 [W1/4 COR SEC 8] NO CORNER EVIDENCE FOUND. RE: MCNABB'S RECORDS REESTABLISHED CORNER POSITION

AT MIDPOINT BETWEEN SEC CORNERS 1/2 MILES NORTH AND SOUTH.

C-05 [NW COR SEC 17] NO CORNER EVIDENCE FOUND. REESTABLISHED THE CORNER POSITION BY A DISTANCE-DISTANCE INTERSECTION, UTILIZING MCNABB'S RECORD DISTANCES TO SEC CORNERS I MILE NORTH AND EAST. ACCEPTED THIS POSITION AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - C-04 SET A BERNTSEN AINB30 ALUM MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.

TANARACK 028 TAMARACK 02" W.BIRCH 3" SURVEY MONUMENT SIGN POST N32°E \$40°E S47°W N45°W 20.28 13.74 1.13' (TO FACE)

C-05 SET A BERNISER AINB30 ALUM MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.

MAPLE 04\* W.BIRCH 08" CEDAR 11" CEDAR 07\* SURVEY MONUMENT SIGN POST N34°W N77°E S46°E 514°W NORTH 45.421 11.46 39.15 20.347 2.47' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A MAIL W/A REFERENCE TAG UNLESS OTHERWISE MOTED.

Signed by Date Surveyor's Michigan License No. <u>16926</u>