SURVEY & REMONUMENTATION

JAN 1 4 1998

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County	
Land Survey Remonumentation	
Peer Group Under Act 345 Of	
P.A. OL 1990 On 12/18 , 199	1
	_
MutoSchwelin.	7
addies Chairman	τ

SECTION For corners in DELTA Corner Code ## Located In: (County) A-03 & A-04 T 42 N R 22 W **Public Land Survey** 42 N R 23 W ____ R _ 2. Property Controlling _ R in Section S. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. __ , Recorded Plat _ Private Claims A-03 [NW SEC 7] A-04 [WI/4 SEC 7] SAME CORNERS AS M-03, M-04 M.P. DAVIS _ , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-03 [NW COR SEC 7] JOHN BURT, DS - 1845 - WOOD POST - (FIR 06"-S20"W-06 LINKS)(CEDAR 06"-N80"W 12 LINKS) E.C.MARTIN, DS - 1852 - (CEDAR 08"-N82"W-11 LINKS) FROM SURVEY OF T42N R23W NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT CORNER MONUMENTATION.

A-04 [W1/4 COR SEC 7] JOHN BURT DS - 1845 - TAMARACK 08*-S79"W-12 LINKS)(TAMARACK 08*-N31"W-18 LINKS)

Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-03 [NW COR SEC 7] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER POSITION BY SINGLE PRO-FORTIONAL DISTANCE BETWEEN & ON LINE WITH THE NW CORNER OF SECTION 6 & THE NW CORNER OF SECTION 31 T42N R22N., WHICH FALLS S22°E 59.6' FROM CHAMPION TIMBER COMPANY'S WOOD POST & LOCATOR TAG.

NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT MONUMENTATION

A-04 [W1/4 COR SEC 7] NO CORNER EVIDENCE FOUND. ESTABLISHED CORNER POSITION ON LINE WITH AND AT MIDPOINT BETWEEN SECTION CORNERS 1/2 MILE NORTH & SOUTH, WHICH FALLS S32°E 68.5' FROM CHAMPION TIMBER COMPANY'S WOOD POST & LOCATOR TAG.



REVISED JAN., 1983

	•					***
C.	Description of mo	nument for co	orner and acce	essories establis	shed to perpetuate locating the position of the corn	ier:
	A-03 SET A BERNTSE	N A1NB30 ALUM	MONUMENT WITH	THE CAP STAMPED	D TO ID THE CORNER POSITION.	
	CEDAR 06"	MAPLE 09*	MAPLE 10*	CEDAR 08"	SURVEY MONUMENT SIGN POST	
	N2O'W	N55"E	838°E	\$27°W	NORTH	
	24.33'	8.71'	29.35'	24.26	2.33' (TO FACE)	
	A-04 SET A BERNTSE	N AINB30 ALUH	MONUMENT WITH	THE CAP STAMPED	D TO ID THE CORNER POSITION.	
	CEDAR 06"	CEDAR 12'	MAPLE 05"	SPRUCE 05"	SURVEY MONUMENT SIGN POST	
	S37°W	845°E	N50°W	N73°E	NORTH	
	13.58'	19.00'	30.15	35.95'	0.97' (TO FACE)	

NOTE: BEARING	GS TO REFERENCE OBJECTS ARE MAGNETIC & D	ISTANCES ARE TO A MAIL W/A REFERENCE THE UNLESS OTHERWISE MOTED.
Signed by	M.P. Dueis	Date 11/25/97
_	igan License No. 16926	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19