SURVEY & REMONUMENTATION

JAN 1 4 1998

Approved By Delta County Land Survey Remonumentation

Peer Group	Under Act	345 Of
A. Of 1990 On		

Chairman

SECTION:

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	or corners in			ŕ
	DELTA	Located In:	Corner Code ##	
	(County)	-		5
1.	Public Land Survey	T <u>42 N R 22 W</u> T R T R T R		9:00, m AM 8 pm 268
2.	Property Controlling	S T R		Marian Comment
	in Section	S T R		AND THE STATE OF T
3.	Miscellaneous	S: T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
		Recorded Plat		A B C D E F G H I J K L N
	E-11 [NW :	SEC 33] E-12 [W1/4 SEC 33]		2 6 5 4 3 2 1 1 3
in cu Ma ab Co	hereby certify that under re- lines 1 and 2 above were i rrent manual of survey instr- magement or by a decree of ove were in conformance wi	quirements of P.A. 74, Michigan P.A. n conformance with regulations a ructions of the United States Depa a Court of Law and/or that the corn the rules of the Michigan Board.	ABER , 19	ed he of the order
NC	OTE: Not more than 4 or this certificate	corners, all in the same town a	and range, may be recorded	11

- Description of original monument and accessories and/or subsequent restoration:
 - E-11 [NW COR SEC 33] E.C.MARTIN, DS 1852 WOOD POST (CEDAR 08"-S25"E-17 LINKS)(CEDAR 12"-N45"W 04 LINKS) D.A.BROTHERTON-1910-FOR TWP. RGAD-ID CORNER POSITION BY OLD BT STAXES IN PLACE NE & SW 33'- SET IRON
 - E-12 [W1/4 COR SEC 33] E.C.NARTIN DS 1852 (MAPLE 08*-S54°E-13 LINKS)(CEDAR 12*-N54°W-37 LINKS) D.A.BROTHERTON-1919-FOR TWP. RCAD-ID CORNER POSITION BY STAKE IN HWY & OLD BT STAKES NE & SW 33'-SET IRON, CORNER FENCE POST S89°E-29'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - E-11 [NW COR SEC 33] FOUND IN PLACE & 12" M/L BELOW ROAD SURFACE A 5/8" IRON PIN AT APPROX. C/L INTERSECTION OF COUNTY ROAD N-S & E & W. NO ACCESSORIES FOUND. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.
 - E-12 [W1/4 COR SEC 33] FOUND IN PLACE & 20" M/L BELOW ROAD SURFACE A 5/8" IRON BAR IN LINE WITH OLD FENCE LINE TO THE EAST. BEARING & DISTANCE CHECKS WELL FROM EXISTING MONUMENT TO THE CORNER FENCE POST (NOW DOWN & IN POOR CONDITION) WITH THAT SHOWN IN THE RECORDS OF BROTHERTON. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - E-11 SET, OVER EXISTING MON, A 5/8 X 18" REBAR W/A 31/4" ALUN CAP STAMPED TO ID THE CORNER POSITION & RAISED TO GRADE W/A MON BOX CEDAR 04" CUT NOTCH-NORTH END CMP CUT NOTCH-SOUTH END CMP SURVEY MONUMENT SIGN POST N64°E N56°W S61°W 853'E

54.65'

29.70

28,60

38.15' (TO FACE) '

E-12 SET, OVER EXISTING MON, A 5/8 X 18" REBAR W/A 31/4" ALUM CAP STAMPED TO ID THE CORNER POSITION & RAISED TO GRADE W/A MON BOX

ELN 03"

TAMARACK 03"

TAMARACK 09"

SURVEY MONUMENT SIGN POST

\$17°E \$85°E N51°E N78°W 78.191 38.26 63,10 27.97' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL W/A REFERENCE TAG UNLESS OTHERWISE NOTED.

Surveyor's Michigan License No. 16926

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975