SURVEY & REMONUMENTATION

JAN 1 4 1998

Approved By Delta County

Land Survey Remonument	ation
Peer Group Under Act 345	
A. Of 1990 On 12/18	199

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Considerated of Sal 74 Mish D 5

For corners in	Filing Requi	rement of ACt 74, MICh. P	'.A. 1970 ·	acring (<u></u>		
DELTA (County)	Located In:	Corner Code ##	C	`			·	-
Public Land Surve	T <u>43 N R 22 W</u> T R	K-05 & M-03	9:00 100	Ole 1 2 2 2 2 2 2 2 2 2 2 2 2 2		7		
 Property Controlling in Section Miscellaneous Property in Sec. 	T R ng S T R S T R S T R		Pett Screen	of Deeds			Numb	er
4. Lot No	, Recorded Plat COR SEC 13] M-03 [NE COR SEC 12]	SAME CORNER AS A-03	2 A	B C D	E F (G H	2_	< L W
do hereby certify that und in lines 1 and 2 above v current manual of survey Management or by a decra above were in conformar	, in a field survey on NOVEN der requirements of P.A. 74, Michigan P.A were in conformance with regulations ar y instructions of the United States Depa ree of a Court of Law and/or that the corn nce with the rules of the Michigan Board hed, re-established, monumented, re-	c. of 1970, the corner points menting rules therefore as required intended in the intended in the lines 3, 4 of Land Surveyors or by a Decre	ioned 6 in the 7 and 5 8 ee of a	-7	21-	15 15 22 27-	23-	13 24 25
NOTE: Not more that on this certification	in 4 corners, all in the same town a icate.	ind range, may be recorded	11	-3132-	33	34	35—	36-

- Description of original monument and accessories and/or subsequent restoration: K-05 [NW COR SEC 13] M.M.HALL, DS - 1853 - WOOD POST - (SPRUCE 12"-N77"W-19 LINKS)(CEDAR 12"-S72"E-20 LINKS) NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT MONUMENTATION
- M-03 [NE COR SEC 12] WM. A. BURT, DS 1841 WOOD POST (SPRUCE 07"-S33"W-29 LINKS)(SPRUCE 09"-S45"E-25 LINKS) ALFRED MILLERD, DS - 1852 - DEAD HEMLOCK 12"-S43°E-93 LINKS)(DEAD HEMLOCK 12"-N29°W-100 LINKS) M.M.HALL, DS - 1853 - WOOD POST - (W.PINE 10"-S35°W-65 LINKS) M.S. McNabe-1930-ID BY STAKE IN RIGHWAY (CORNER FENCE POST-NORTH-17.0')(IRON REFERNCE MONUMENT SOUTH 33.0') BILLY BUCKLER, DNR-1955-RESET IRON PIN 17' SOUTH OF CORNER FENCE POST-SET DNR REFERENCE MONUMENT SOUTH 33' REC'D L.3 PAGE 86
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-05 [NW COR SEC 13] FOUND IN PLACE & 20" H/L BELOW COUNTY ROAD SURFACE A 5/8" X 15" IRON PIN W/A 1" SQUARE HEAD BY PERSONS UNKNOWN. ID CORNER POSITION BY COUNTY ROAD IMPROVEMENTS E & W AND ANCIENT FENCE LINE OCCUPATION TO THE SOUTH. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.
 - M-03 [NE COR SEC 13] DNR 1955 MONUMENT HAS APPARENTLY BEEN DESTROYED IN ROAD IMPROVEMENT. RESTORED THE SAME FROM THE DNR REFERENCE MONUMENT FOUND 33' TO THE SOUTH & THE REMAINS OF MCNABB'S CORNER FENCE POST 17' TO THE HORTH. ACCEPTED AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.

13.50

79.891

100.301



C.	Description of	monument for corr	ner and accessorie	s established to perpetual	te locating the position	of the corner:
	K-05 SET, OVER E SPRUCE 12* S27°W 28.96'	XISTING MONUMENT & CUT ON W END CMP NO8°E 27.43'	4" BELOW GRADE A ! MAPLE 06" N47°E 68.78'	5/8" X 18" REBAR W/A 31/4" SURVEY MONUMENT SIGN POST SOUTH 17.30' (TO FACE)	ALUM CAP STAMPED TO ID	THE CORNER FOSITION.
	M-03 SET, 4° BEL TAMARACK 12 S68'E			TALUM CAP STANPED TO ID S DNR REFERENCE MONUMENT		POST

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL W/A REFERENCE TAG IN THE OBJECT UNLESS OTHERWISE NOTED.

33.001

Surveyor's Michigan License No. 16976

16.90' (TO FACE)