## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 1979 1979 29 Alt (3: 3)

| For corner  | s in  | or AGE 74, 19   | acit. P.A. 1970  |
|---|---|---|--|
| <u>Dickin</u><br>Wauced                             | Son Located In: Corner Code (County) ah Twp.  | )#<br>-   | REGIO PER CUI DEFEOS<br>DIOKOS SES PORTES Y<br>POU PER CONTROLOS   |
| Propert in Secti     Miscella                       |   | <del>NS.</del>  | Register of Deeds Stamp & File Number  |
| 4 Lot No  | , Recorded PlatSECTI  | <i>C</i> IALI   | Section of the feature of the featur |
| 5. Private  | Claims  | Ola   | A B C D E F G H I J K L  |
| conformance United States that the corn Board of La | F. Perkins, in a field survey on Oct. 12, 1999 of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in with regulations and rules therefore as required in the current manual Department of the Interior, Bureau of Land Management or by a decier points mentioned in lines 3, 4 and 5 above were in conformance vind Surveyors or by a Decree of a Court of Law; established, reund as expressed below: | lines 1 and 2 and 1 and 2 and 1 and 2 and 1 and | above were in ructions of the 5  |
|   | ot more than 2 corners, all in the same town and range, may be this certificate.  | recorded  | 9<br>10 30 29 28 27 26 25<br>11<br>12 31 32 33 34 35 36  |
| A. Descrip  | tion of original monument and accessories and/or subseque   | nt restoration  |  |
| E-10  | Corner 29/28  Post by J.H. Mullett, D.S. 1849  Original Bearing Trees  Maple 3" N48°W 05 Lks.  Maple 3" S35°E 08 Lks.   | G-10  | the Corner 28/27 Post by J.H. Mullett, D.S. 1849 N. Side Windfall Original Bearing Trees Birch 6" S11°E 10 Lks. Elm 16" S87°E 15 Lks.  |
| B. Descrip  | tion of corner evidence found and/or method applied in resto  | oring or reesta   | ablishing corner:  |
| E-10  | No Evidence of Original Corner<br>or Accessories Found.<br>Found K.C. Corp. 1" Pipe Marker<br>with 4" Brass Cap as Established<br>by Neal Sperhake, RLS in 1963.<br>W.Pine N55°W 33½L.(Found)<br>Corner Report #760   | G-10  | No Evidence of Original Corner or accessories found. Corner Location established by Single Proportionate Method between Section Corner 1 Mile North and 1 Mile Southoration By THE DICKINSON COUNTY SUATED BY THE DICKINS |
| C. Description                                      | on of monument for corner and accessories established to p  | erpetuate loc   | The state of the s |
|   | Accepted Marker described in B above.  New Witnesses W.Pine 12" S77°E(M.B.) 4.19' Nail/Tag W.Pine 16" N52°W(M.B.) 22.07' Nail/Tag R.Pine 12" N5°E(M.B.) 47.38' Nail/Tag R.Pine 18" S14°W(M.B.) 42.96' Nail/Tag Placed Carsonite Marker 1.0' South   | G-10  | Set 2½" Stamped D.C.Remon. Marker as described in "B" above. New Witnesses Maple 7" N27°W(M.B.) 26.24' Nail/Tag Maple 12" N55°E(M.B.) 46.85' Nail/Tag Maple 7" N69°W(M.B.) 31.76' Nail/Tag Ash 4" S03°W(M.B.) 21.53' Nail/Tag  |
| N   | 12 PD   |   | , , , , , , , , , , , , , , , , , , ,  |
| Signed by   |   |   |  |
|   |   |   |  |

Liber 2

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN., 1983
REVISED OCT., 1995