SUFIVEY & REMONUMENTATION

APR 07 1995 LAND CORNER RECORDATION CERTIFICATE COMMISSING Requirement of Act 74, Mich. P.A. 1970 For corners in Dickinson Located In: Corner Code =## Public Land Survey Section 2 T 39N R 28W **Property Controlling** in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_\_ Recorded Plat \_ Private Claims \_ 1/4 corner Sections 2 & 11 October 24 19 94 I. John R. Garske , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Original survey by James H. Mullet, D.S., in August 1849. Set post B.T.s: sugar 15" - S40°W, 24 links; Ironwood 10" - N8°W, 34 links. 1912 - M. Bacco, Dickinson Co. Rd. Commission, set cedar post from remaining original sugar maple B.T. 1917 - C.I. found Bacco's post in good condition. 1938 - W.C. Johnson survey shows corner but not what was found or set. 1960 - Champion International (Kimberly Clark) map indicates iron pipe at 1/4 corner. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: August 31, 1993 - I found 1 1/2" O.D. iron pipe at corner location. Corner was located by chaining 2637 feet from the monumented corner east. I am accepting the iron pipe as marking the true corner because of the good chain of evidence and its use and acceptance over many years. ACCEPTED BY THE DICKINSON COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 1990 AT A MEETING HELD ON 345 OF COUNTY REPRESENTATIVE C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set Dickinson County aluminum monument inside old 1 1/2" pipe. Monument is flush with ground. Established following references: 6" sugar maple - N20°E, 35.75 feet; 5" sugar maple - S43°E, 11.18 feet; carsonite rail - south, 1.63 feet; 5" sugar maple - S41°W, 31.30 feet; 9" sugar maple - S86°W, 22.62 feet. GARSKÉ LAND

der 2 J-3 Page 13=

Signed by

Surveyor's Michigan License No

ÑVEYORS, JAN. 28, 1971 REYISEO MAY 14, 1975 REVISED JAN., 1983

SURVEYOR No. 28410