SI	EC	TI	O	١	į
~	_~		-	•	*

LAND CORNER RECORDATION CERTIFICATE

RECORDED

For corners in	Filing Requiren	nent of Act 74, Mich. P.A. 1970	1997 DEC 10 PM 3: 57	
Dickinson (County)	Located In:	Corner Code #	10 11 0.07	
Norway Twp.			REGISTER OF DEEDS	
Public Land Survey	T <u>40N</u> R <u>29W</u> T R T R	D-5 D-3	PON MEN SHAME COMMY	
2. Property Controlling in Section	T R S T R S T R			
3. Miscellaneous Property in Section	ST R ST R	Beg	ister of Deeds Stamp & File Number	
Property in decidin	3 1 n			
4. Lot No	, Recorded Plat		- ARCDEEGHIIVI	
5. Private Claims				
			2 - 6 5 6 - 7 - 7 - 7 - 7 - 7 - 7 - 7 - 7 -	
	•		3 T T T T T T T T T T T T T T T T T T T	
. Robert E. Porkin	NO. 15 - 6-14 (1979)	84 11 407	4 7 8 9 10 11 12	
t, Robert F. Perkins, in a field survey on Sept. 11, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned				
in lines 1 and 2 above were in	n conformance with regulations and rule	s therefore as required in the current	6 18 17 16 15 14 13	
manual of survey instruction	ons of the United States Departmen	t of the Interior, Bureau of Land		
	of a Court of Law and/or that the come ce with the rules of the Michigan Boan		6 19 20 21 22 23 24-	
	stablished, re-established, monumented		9	
as expressed below:		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	10 30 29 28 27 26 25	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11	
on this certificate	•	•	12 31 32 33 34 35 36	
A Description of origin		Man and as annual make make	13	
A. Description of origin	al monument and accessories and 8	or subsequent restoration:		
D-5 1 Corner	17	D-3 ½ Corner 8	<u>'</u>	
Post by J	ames Mullett, D.S. 1849	•	mes Múllett, D.S. 1849	
	Bearing Trees		Bearing Trees	
	S13°W 10 Lks.	Black Ash	10" N21°E 22 Lks.	
W.Pine 10	" N10°W 15 Lks.	Hemlock _{noo.}	PALD BY AND DICHNSON COUNTY	
		SUA	VEY PEER GROUP AS N PUBLIC , CT	
	-	2/5	OF 1990 ALA MEET.	
		ຳ້ລ	<u>9-97</u>	
P. Description of some	v aritikaina karmalanaktar maska ala a		RAP	

- Description of corner evidence found and/or method applied in restoring or reestablishing corner: COUNTY REPRESENTATIVE
- **D-5** No evidence of Original Corner or Accessories Found. Found 1" Iron Pipe with 4" D.N.R. Brass Cap set by D.C. DeLaMater, RLS in 1955. No Witnesses available in 1955. (Old Report #46)
- No evidence or Original Corner or Accessories Found. Found 1" Iron Pipe with D.N.R. 4" Brass Cap set by D.C. DeLaMater, RLS in 1955. 1955 Bearing Trees: Hemlock 16" S15°W 26 Lks. Spruce 8" S63°E 71 Lks. Rock Face North 61 Lks. (Old Report #50)
- C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:
 - D-5 Found and Accepted above described Monument. New Witnesses: Cedar 2" N86°E (M.B.) 9.86 Cedar 4" S15°E (M.B.) 12.42 S67°W (M.B.) N18°E (M.B.) Cedar 4" 8.281 7" Fir 15.45 Carsonite Marker North 1.0
- Found and Accepted above described Monument. New Witnesses:

Maple 8" N41°E (M.B.) Maple 8" S85°W (M.B.) 19.75'

- * Hemlock 16" S15°W 17.60'
- Spruce 12" S63°E 46.78* Carsonite Marker North 1.0 Rock Face North 40.3'
- * Existing 1955 B.T.

Surveyor's Michigan License No.

Nov. 19, 1997 Date