SUMVEY & REMONUMENT

MAY 07 1097

RECORDED

1996 DEC 18 AM 11: 15

For corners in COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Dickinson (County)	Located In:	Corner Code #	REGISTER OF DEE DIGKINSON COUNT IRON MOUNT AIM MILA
Public Land Survey	T <u>40N</u> R <u>29W</u> T R T R T R	<u>K-7</u>	
2. Property Controlling in Section	S T R S T R		(9)
Miscellaneous Property in Sec.	S T R S T R		

Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat	
5. Private Claims		

in a field survey on 8 November Michael Mileski _, 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- K-7; Section Corner common to Sections 13, 14, 23, and 24,T40N,R29W;

See back of form.

AGGEPTED BY THE DICKINSON COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD

12-17-96 TE ROP Description of corner evidence found and/or method applied in restoring or reestablishing corner:

COUNTY REPRESENTATIVE

K-7; Section Corner common to Sections 13, 14, 23, and 24, T40N, R29W;

Found a 2" diameter iron pipe at ground level alongside of which is the 1" x 42" galvanized iron pipe with 4" brass cap as set by Mr. DeLaMater in 1953. This monument was found to be in agreement with Mr. DeLaMater's new bearing trees as described in Part A. Replaced Mr. DeLaMater's monument with a standard county monument set inside the 2" diameter iron pipe. Accepted as a careful and faithful perpetuation of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- K-7; Section Corner common to Sections 13, 14, 23, and 24, T40N, R29W;

Set a 5/8" x 36" aluminum rod with a 3" aluminum cap stamped as to location projecting 4" above the ground.

Set 7" spike	NW/side	5" Cedar	N38°E	27.83'
Set 7" spike	NE/side	6" Cedar	S55°E	18.84'
Set 7" spike	NW/side	6" Black Spruce	S35°W	17.47'
Set 7" spike	NE/side	6" Cedar	N51°W	14.68'
		Location Post	North	3.0'

All of the above new bearing trees are marked with upper and lower blazes.

The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.

OF MICHIG MICHAEL D MILESKI PROFESSIONAL SURVEYOR No. 39091 OFESSION

Signed by Surveyor's Michigan License No. 39091

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971