MAR 0 3 1998

SECTION	
---------	--

## LAND CORNER RECORDATION CERTIFICATE

RECORDED

Filing	Requirement	of Act	74.	Mich.	P.A.	1970

man nee to PM 3:56

For corners in	rung nequiem	- 1910 W 2. 24	
Dickinson (County)	Located in:	Corner Code #	
Breitung Twp.			AFOUNTEP OF DEEDS
1. Public Land Survey	T <u>40N</u> R <u>30W</u> T R T R T R	K-9 K-10	REGISTER OF DEEDS DICKINGON COUNTY ROWNIENT OF MEEDS
2. Property Controlling in Section	ST R ST R		
Miscellaneous     Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, F	Recorded Plat		
5. Private Claims			A B C D E F G H I J K L
			3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3

K - 10

K-10

I, Robert F. Perkins, in a field survey on Oct. 9 . 19 97 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

## ř

- Description of original monument and accessories and/or subsequent restoration:
  - Corner Common to Sections 23-24-25-26 Post by James H. Mullett, D.S. 1849 Original Bearing Trees B1k. Oak 12" N15°E 16 Lks. 12" S20°W Aspen 21 Lks.

corner Common to Sections 26/25 Post by James H. Mullett, D.S. 1849 Original Bearing Trees Sugar 10" S70°E 13 Lks. Birch 10" N12°W 14 Lks.

- B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:
  - K-9 No Evidence of Original Corner or Accessories Found. Found 1" Boat Spike projecting ± 2" out of Ground. Also 2 Existing Scribed Witness Trees (Not Original). Corner is 2654.88' East of 1 Corner 23 and 2624.73' 26 North ! Corner Sec. 25/26. Corner Location Researched in 1996 Program.

No Evidence of Original Corner or Accessories Found. Corner Researched in 1996 Program.

> ACCEPTED BY THE DICKINSON COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

DA GAT COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9 Accepted above Described Boat Spike as K-10Best Available Evidence of Corner. New Witnesses: Maple 3" N19°E(M.B.) 23.80' Nail/Tag Maple 4" S84°W(M.B.) 4.35' Nail/Tag Maple 12" S71°E(M.B.) 11.57' Nai1/Tag(Ex.BT) Maple 14" S30°W(M.B.) 11.30' Nail/Tag Carsonite Marker South 0.5 Set 22" Stamped D.C. Remon. place of above Described Book Spike Set 22" Stamped D.C. Remon. Corneruda

12027

\*

Established Corner 2624.75 feet Due South of Section Corner at Point that is 905 feet North of the Centerline of the Former E.I.M.& W. RR as indicated on Railroad R.O.W. Map dated 1892. Set 21" Stamped D.C. Remon. Corner at above Location. New Witnesses:

16" S73°W(M.B.) 0ak 19.26' Nail/Tag 811 S45°E(M.B.) 19.54 Nail/Tag 0ak 8" N75°E(M.B.) 8.92'Nail/Tag Sugar Sugar 8" N59°W(M.B.) 30.35'Nail/Tag E997 DateCarsonite Marker North 1.0'

70 B

Surveyor's Michigan License No.

ROBERT **PERKINS** IN SONAL SUR

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1975