LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(<u>DICKINSON COUNTY</u>)		
FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY T. 40 x., R. 30 w.	#L-3	
2. PROPERTY CONTROLL- 1 ,T. 40 N. R. 30 W.	#15 & 16	
3. MISCELLANEOUS PROPERTY IN SECTION, T, S., R W.		
4. LOT NO, RECORDED PLAT		
5, PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 31, 19 79, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Corner L-3 (1/4 corner between Sections 1 & 12, T40N, R30W):		
Wood post (Not found. No subsequent monuments found.) W. Pine 4 N28W 13 (Not found. No subsequent accessories found.)		
Sugar 4 S34E 20 (Not found. No subsequent accessories found.) Corner 15 (West 1/16 corner between Sections 1 & 12, T40N, R30W) and		
Corner 16 (East 1/16 corner between Sections 1 & 12, T40N, R30W): Neither of these 2 corners set in original survey nor subsequently, apparently.		
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Corner L-3: Restored on line between original sec. cor. 40.388 ch. E and original sec. cor. 40.388 ch. W.		
Corner 15: Established on line between Sec. Cor. 20.194 ch. W and 1/4 cor. 20.194 ch. E. Falls on side of north-facing slope of a high granite knob.		
Corner 16: Established on line between Sec. Cor. 20.194 ch. E and 1/4 cor. 20.194 ch. W.		
C. Description of monument for corner and accessories establi	shed to perpetuate locating the	position of the corner:
Corner L-3: 1" I.D. x 36" iron pipe with 3 Red Pine 12 N70°W (mag.) 14.6 Red Oak 20 S62°W (mag.) 23.5 Declination 4° 50° West.	3/4" aluminum cap. ft. "1/4S, NBT"	position of the content
Corner 15: Chiselled on rock outcrop, wi W. Pine 15 N24°E (mag.) 12.6 Cedar 6 S64°E (mag.) 11.0 Cedar 4 S84°W (mag.) 13.8	ft. "1/16S, BT" ft. "1/16S, BT"	n over it. Distances horizontal. Declination 3 ⁰ 20' West.
Corner 16: 1" I.D. x 36" iron pipe with 3 Red Oak 5 N110W (mag.) 10.0 ft.	3/4" aluminum cap. "1/16S, BT"	
Red Oak 5 S19°E (mag.) 21.0 ft.	"1/16S, BT" DATE	Declination 5° 00' West.
SURVEYOR'S MICHIGAN REGISTRATION NO		(SEAL)
FOR STATE AND UNITED STATES AGENCIES:		Millian Co
SIGNED BYCHIEF OF SURVEY PARTS	DATE	- 0.
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAI Arthur O. Eng	ND SUMPEYOR	March 4 1980
Michigan Department of Natural Resources		
SURVEYOR'S MICHIGAN REGISTRATION NO. 13581		

FORM APPROVED BY MICHIGAN STATE SOARD OF REGISTRATION, JAN. 28, 1971 REVISED MAY 14, 1975