SURVEY & REMONUMENTATION

MAR 0 3 1998

RECORDED

		LAND CORNE	RECORDATION CER	INFICATE	
For co	rners in SECTI	ON Filing Require	ment of Act 74, Mich. I	P.A. 1970 1797 DEC 10 PM 3: 51,	
Dick	cinson (County)	Located In:	Corner Code #	1	
	tung Twp.		25	750101111111111111111111111111111111111	
1. Pul	blic Land Survey	T4 <u>0N</u> R <u>30W</u> T R T R T R	M.C. 36 W. of L-11 #003 M.C. 35/36	REGISTER OF FEEDS DICKINDON GOUNTY RON SECRET A SECRET	
in S	Section Section	ST R ST R	N. of K-12	Register of Deeds Stamp & File Number	
Pro	perty in Section	S R		register of Deeds Stamp & File Number	
		Recorded Plat		A B C D E F G H I J K	
5. Priv	vate Claims			2 6 5 4 3 2	
				3	
				4-789-1011	
I, Rob	ert F. Perkins	s, in a field survey on quirements of P.A. 74, Michigan P.A.	Oct. 29, 19 97	5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
in lines 1 manual Manage 5 above Decree	1 and 2 above were in o of survey instructions ment or by a decree of were in conformance	conformance with regulations and rules of the United States Department a Court of Law and/or that the control with the rules of the Michigan Boalblished, re-established, monumented	les therefore as required in the int of the Interior, Bureau her points mentioned in lines and of Professional Surveyors	or by a 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
NOTE:	Not more than 4 coon this certificate.	rners, all in the same town and r	ange, may be recorded	11	
A. De	scription of original	monument and accessories an	d/or subsequent restorati	on:	
ME	ANDER CORNER	<u>25</u> 36	MEANDER	CORNER 35/36	
		Mullett, D.S. 1849		James H. Mullett, D.S. 1849	
	iginal Bearing			1 Bearing Trees	
	dar 4" N50°E marack 10" S7			" S7°E 32 Lks. k 8" S28°W 33 Lks.	
la	marack 10° 57	U E 25 LKs.	Tamarac	ACCEPTED BY THE DICKINSON COUNTY PEER GROUP AS THE CORNER UNDER MICHIGAN PUBL 345 OF 1990 AT A MEETING HALL	
B. Des	scription of corner e	vidence found and/or method a	applied in restoring or ree	stablishing corner Person	
	<u>25</u>		-	COUNTY REPRESENT.	
M.		riginal Corner	M.C. 3	5/30 ence of Original Corner	
	Accessories F			ssories Found.	
It	appears from	the Remains of Trees		ars from the Remains of Trees in	
		he Lake Level was rais		er that the Lake Level was raised	
		sequent to the Origina by the construction of		time subsequent to the Original probably by the construction of	
		ol Structure. As a		let Control Structure. As a	
		nal Meander Corners		the Original Meander Corners	
	re Lost.		were Lo	st.	
	rner Location mon. Program.	Researched in 1996		Location Researched in 1996 Program.	
C. Des	scription of monume 25	nt for comer and accessories	stablished to perpetuate	locating the position of the corner:	
М.			M.C. 3	5/36	
Set	West of $\frac{1}{4}$ Corner $\frac{25}{36}$ on alignment of ancient Due		2.00' Set 2½"	Set 2½" Stamped D.C. Remon. Corner 1291.80	
We:			ient Due Nor	th of 1 Corner 35 and 36, 4' from	
			and High Wa	ter Mark.	
	s a Bearing of w Witnesses:	307 33 43 W.		nesses: " S37°E(M.B.) 10.68' Nail/Tag	
		(M.B.) 2.25' Nail/Tag	cedar 3	" N46°W(M.B.) 7.76' Nail/Tag	
Sp	ruce 7" S36°E	(M.B.) 19.38' Nail/Tag	Gedar 3	" S03°E(M.B.) 37.22' Nail/Tag	
Ce	dar 6" S32°W	(M.B.) 17.47' Nail (Re) (M.B.) 10.65' Nail (Re)	Cèdar 3	" S38°W(M.B.) 31.88' Nail/Tag ine dirt Road ± 16' South	
Signed I	by Francis	OBANT	ROBERT * * E Date	Nov. 26, 1997	

12027

Surveyor's Michigan License No.

LIBER 002 PAGE 338

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983