	-	_
Opm	DD T	o THRASW
	1	/

For corners

RECORDED

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1970 DEC 14 PH 12: 25

•	t.								
Nor	(County) way Twp.	Located In:	Corner Code #			REGIST	TEA OF SET	HDS Try	
1. Pub	olic Land Survey	T <u>41</u> R_ T R_ T R_	29W <u>M</u> -4 M-5	- SURV	VEY &		12		
in S	perty Controlling ection cellaneous	STR_ STR_		- NOV I	5 1999	,			
	perty in Sec.	s TR_		SECT		ster of Dee	ds Stamp &	k File Nu	mber
4. Lot I 5. Priva	No , Recor	ded Plat			, A B	CDE	F G H	ΙJ	 < г. і
1 Dah					2 6-	5	-43		
i, <u>Robert F. Perkins</u> , in a field survey on <u>Nov. 9</u> , 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Remove of the In					<u> </u>		9———10— ————————————————————————————————	11-	-12-
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				7	17-	16	14-	—1 ¹ 3—	
NOTE: Not more than 2 co on this certificate.		ers, all in the same town and range, may be recorded			9 10 30	20	21 22	23	-24-
					11 -31-	32	3334	35_	
									1 1

M-5

M-5

- A. Description of original monument and accessories and/or subsequent restoration:
 - East & Corner Section 12 Post by Wm. A. Burt, D.S. 1846 Original Bearing Trees Cedar 6" S44°E 12 Lk. Cedar 14" N57°W 35 Lk.
- Southeast Corner Section 12 Post by W. A. Burt, D.S. 1846 Original Bearing Trees Fir 6" S80°W 7 Lk. Fir 8" N68°E 15 Lk.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner.
 - M-4 No Evidence or Original Corner M-5 or its Accessories Remain. Found 1" Iron Pipe Monument with 4" D.N.R. Cap set by Billy D. Buckler, RLS from G.L.O. BT's in 1957. (01d Report #291) 1957 Bearing Trees: Cedar 24" N71°W 80 Lk. (Found) Cedar 15" S33°W 11 Lk. (Found)

No Evidence of Original Corner or Accessories Found. Found 1½" Iron Pipe Found by Billy D. Buckler, RLS in 1957 and referred to in Old Corner Report #290. 1957 Bearing Trees: Tamarack 8" S65°E 36 Lk. (Found) S20°W 54 Lk. (Found) Tamarack 7"

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Found and Accepted Pipe Marker described in "B" above. Witnesses: Cedar 30" N68°W(M.B.) Cedar 30" S32°W(M.B.) 53.10 Ex. B.T. 7.45' Ex. B.T. Cedar 12" \$25°E(M.B.) 25.53' Nail/Tag 18.48' Nail/Tag Fir 6" N71°E(M.B.) Placed Carsonite Marker T. 0. South

Found and Accepted Corner described in "B" above. Set 31" Stamped D.C. Remon Corner inside of Existing Iron Pipe. New Witnesses: Spruce 8" N77°W(M.B.) 22.23' Nail/Tag Spruce 6" N63°E(M.B.) 20.52' Nail/Tag Tamarack 12" S22°W(M.B.) 35.95' Nail/Tag Tamarack 10" S67°E(M.B.) 24.30' Nail/Tag Placed Carsonite Marker 1.0' South

Treyor's Michigan Liceose Note 1292E DICKINSON BRINS

Date Nov. 20, 1998

SURVEY PEER GROUP AS THE OFFIND ALL COINER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 12-7-98

COUNTY REPRESENTATIVE

Lihor 2

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975 REVISED JAN., 1963 REVISED OCT., 1995