## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 41 NR 28-29 W

				Dickinson	(	COUNTY
DESCRIPTION	OF	CORNER	1/4 corner	between Sec. 1s 7-	12	
DESCRIPTION	OF	CORNER	MONUMENT	l" pipe with 4"	brass cap	
WITTNESSES	то	CORNER	24" Cedar	N 71 W	80 links 11 links	
			15" Cedar	S 33° W	ll links	
				"1/4 S NBT	#	
						. <b>.</b>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from one cedar B.T. bearing N 57° W 35 links in poor condition(down). Scribe marks visible, and one cedar B.T. bearing S 44° E 12 links in poor condition. Found notch in remains.

Found magnetic compass somewhat erratic in this area.

Found by Forestry Division Survey crew.

SURVEYORS SEAL

SIGNED Silly D. Buckler DATE 8/2/57
REGISTERED LAND SURVEYOR