## RECORDED

133 DEC 20 FM 2: 34

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

<u>.</u>		Filing Requi	rement of Act 74, Mich. P.A	. 1970 ·	
For corners  Dickinson	s in ·	Located In:	Corner Code ##	RECIGION OF UNION	MUUTTY
o í som su	(County)		30.110.0000	HON Visit of	11.1468 <b>0</b> 1
·	Land Survey y Controlling	T 41 N R 29 W T 41 N R 29 W S T R S T R	I=6 J=7 K=5 K=6	ACCEPTED BY THE DICKINSO SURVEY PEER GROUP AS TH CORNER UNDER MICHIGAN P 345 OF 1990 AT A MEETING 6-7-94 COUNTY REPRES	E OFFICIAL PUBLIC ACT 3 HELD ON
3. Miscell		S T R		Register of Deade Stome 9 E	Sila Numbar
	y in Sec.	S T R		Register of Deeds Stamp & F	ne number
4. Lot No.	, R	ecorded Plat		A B C D E F G	
5. Private	Claims	, , , , , , , , , , , , , , , , , , ,		A B C D E F G	HIJKLM
				3 6 5 4 4 3	3-1-2-1-1-1
F. mand 0	W11				10-11-12
do hereby ce in lines 1 an current mand Management above were i	rtify that under req d 2 above were in ual of survey instru or by a decree of a n conformance with w; established, re	uirements of P.A. 74, Michigan P.A. conformance with regulations a actions of the United States Depail Court of Law and/or that the corn have rules of the Michigan Board.	ctober , 19 93  to of 1970, the corner points mention and rules therefore as required in rtment of the Interior, Bureau of La er points mentioned in lines 3, 4 an of Land Surveyors or by a Decree of monumented, recovered, found	ned the 7 18 17 16 16 17 16 16 17 16 17 16 17 16 17 16 17 17 16 17 17 17 17 17 17 17 17 17 17 17 17 17	22 23 24 27 26 26 26
	t more than 4 co this certificate.	orners, all in the same town a	ind range, may be recorded	12 31 32 33	343536
A. Descrip	otion of original n	nonument and accessories ar	nd/or subsequent restoration:	John Burt/Lucius Lyon 4/27/1	1840
I-6 Origi	nal Witnesses:	Set post Quarter sections: Cedar 8 N61E 12 1ks.	n corner between Sections 1	4,2775 4 & 15.	.049
		Set cedar post Quarter : lks: Y. Pine S62W 10 lks	section corner between Sect •	cions 14 & 23.	
		Set cedar post corner of s: Cedar 14 S54E 15 1ks.	f Sections 11,12,13 & 14.		
Cedar B. Descrip I-6 DNR N	· 24 N47W 12 1k tion of corner ev IBT's: Set one	s: Cedar 30 S32E 18 lks. idence found and/or method -inch iron pipe/brass cap	section corner between Sect applied in restoring or reestab midway on line between Sec S26W 40 lks(fd.): Cedar 7	lishing corner: tion corners North & South.	1 4 ,
		-inch iron pipe/brass cap s(fd. stump): Aspen 8 Wes	midway on line between Sec st 41 <sub>,</sub> lks(fd. stump).	tion corners East & West.	
			by double proportion?Section 8 N47W 27 1ks(fd.): H.Mp	on corners North, East, South 1 8 N43E 37 lks(fd.)	& West.
			midway on line between Sec m 7 N27W 69 lks(fd./dead)	tion corners North & South.	1
I-6 Found	DNR iron pipe,	/brass cap & post.		ting the position of the corner: Ma ments to 16d nail in notch/si Cedar 7 N36W 9.75	4
		/brass cap southeast of in S25W 77.70: R.Pine 9 S42E	tersection of fire lanes. 52.85: Aspen 6 N60W 45.4	0: Aspen 5 N16E 42.10.	
	Found DNR iron pipe/brass cap at squared/scribed H.Maple. NBT's: H.Mpl 10 N47W 18.25: H.Mpl 12 N44E 24.75: H.Mpl 7 East 34.40: Squared Mpl 13 S42W 1.90.				
NBT's	_	BE 14.35: Spruce a NEBWY	4.83: Spruce 10 S74W 48.6	0: B. Ash 3 N48W 7.53.	
Signed by _e	Europet C	Muller MULLER	Data Dara	ember 17, 1993	
	lichigan License	No 15/02 SURVEYO	R Date		
	norngan Elberiae	No. 15408		IRM APPROVED BY MICHIGAN STATE BOARD OF LAND S	URVEYORS, JAN, 28. 1971 REVISED MAY 14. 1975 REVISED JAN,, 1983