Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established on line between two Section Corners and at 40.00 chains from South Section Corner. The North half is short because of error in measuring in the original survey.

Note: Pipe is 2 links South of Actual Corner.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Silly D. Buckler DATE January 3, 1962
Billy D. Buckler