## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T. 41 NR \_ 29 W\_

	- h'r'c'k' f B a o B COON!
DESCRIPTION OF CORNER	Section corner common to Section 8,9,16,17
DESCRIPTION OF CORNER	MONUMENT_1" Pipe with 4" Brass Cap
WITNESSES TO CORNER	8" Cedar (S 8 NBT) N 22° W 28 Links
:	5" Tamarack (S 9 NBT) N 32° E 46 Links
•	7" Tamarack (S 16 NBT) S 58° E 30 Links

RESTORED. This corner was replaced at old wood post. Found blazes north, south and west from corner. No evidence of original bearing trees. Distance checks west to stream and east to ridge.

Corner was placed and witnessed September 24, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Silly & Suckles. DATE 4/29/60
REGISTERED LAND SURVEYOR

Billy D. Buckler