## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filir	ng Requirement of Act 74, Mic	h. P.A. 197	0					
Dickinson (County)	Located In:	Corner Code #							
1. Public Land Survey	T <u>411</u> R T <u>411</u> R TR	299 610							
Property Controlling in Section     Miscellaneous Property in Sec.	TR S TR S TR S TR			Regist	er of De	eds Str	amp &	File Nu	mber
4. Lot No, Record	ded Plat		•	1 A B (	D 9	F G	н :	I J k	C L
4 <u>Stanhan J. Szyszkoski</u> .	, in a field surveyon ,	Sep 10 1998 do hereby state	e that under	3	- 5 - 8	4 	- 3 10		— i -
requirements of P.A. 74, Michigar conformance with regulations and United States Department of the Ir that the corner points mentioned i	n P.A. of 1970, the com- rules therefore as require nterior, Bureau of Land M in lines 3, 4 and 5 above a Decree of a Court o	er points mentioned in lines 1 and 2 ab d in the current manual of survey instruc- lanegement or by a decree of a Courl of I were in conformance with the rules of the f Law; established, re-established, mo	ctions of the Law and /or ne Michigan	5 10 7 8 19	17	-16 -21	15	-14	— -   -   - 
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			9	29	28	_27_	—26—		
		es and/or subsequent restoration:		11 31 31 31 31 31 31 31 31 31 31 31 31 3	32	33	_34	35	36

- (69) Corner common to Sections 21-22-27-28. Corner recorded in 1956 by Billy D. Buckler, RLS: "One Y. Birch stump in place (probable B.T.). Distance checks North, East and South to rock ledges and West to lake. Corner placed and witnessed August 31, 1955. Corner monument: 1" pipe with 4" brass cap. Witnesses: 15" Yellow Birch M19W 19 links, 9" Soft Maple S36E 14 links."
- (610) Quarter corner common to Sections 27-28. Corner recorded in 1956 by Billy D. Buckler, RLS: "Corner found by Forestry Division Survey Crem while working in this vicinity. One M. Pine and one Y. Pine B.T. in fair condition, (Y.Pine down). This M. Pine B.T. marked by John Burt, September 28, 1849. Has date noted on tree. Corner placed and mitnessed August 31, 1955. Corner monument: 1° pipe with 4° brass cap. Mitnesses: 12° Hemlock S62M 66 links, 12° Cedar N2E 55 links."
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (69) Recovered the 1955 monument as described, a 1" iron pipe capped with a 4" dia. brass Michigan Dept. of Conservation tablet, in good condition, and at record bearing and distance from the 1955 witnesses, both in good condition. Left the monument in place and marked new witnesses as described below. Corner recovered and rewitnessed by B.Wheeler and D.Lampela, Baraga District Office.
  (G10) Recovered the 1955 monument as described, a 1" ID iron pipe capped with a 4" dia. brass Michigan Dept. of Conservation tablet, in good condition, set in a mound of rock perched on the exposed bedrock, and at record bearing and distance from the 1955 witnesses, both recovered in good condition. Recovered the rotting remains of the original B.T.s, Y. Pine 16 M58M 50, and M.Pine 18 S64E 25, at record bearing and distance. Left the monument in place and marked two new witnesses as described below. Corner recovered and rewitnessed by B.Wheeler and D.Lampela, Baraga District Office.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Bearings are magnetic.

(69) Fd. 1" pipe with 4" brass cap.
Blazed and scribed the following:
11" Maple M82E 13.9" "S22 M81"
8" Cedar S88M 21.4' "S28 M81"
The 1955 witnesses:
20" Y. Birch M15M 19 links. Old blaze
11" Maple S31E 14 links. do
Bearings are magnetic. Distances are to notch in lower blaze.

essories established to perpetuate locating
(G10) Fd. 1" pipe with 4" brass cap.
Blazed and scribed the following:
10" Maple S82E 15.2" "1/45 M87"
9" Sugar M31N 39.8" do
Distances are to notch in lower blaze.
The 1955 witnesses:
15" Hemlock S63N 66 links
14" Cedar NO6E 55 links

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

Signed by Stephen Surveyor's Michigan License No. 33986

Date