LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich P & 1970

For corners in		Birodan olilotti oli kot 1-4, taoti. 1-2	, , , , , ,						
Dickinson	Located in:	Corner Code #							
(County)									
1. Public Land Survey	T <u>41#</u> R_ TR_ TR_								
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S25T_111 R_ STR STR STR	29N 9	F	legiste	r of De	eds Si	temp é	i File Nu	umber
4. Lot No, Records. Private Claims	rded Plat		, <u>A</u>	вс	D E	F	G H	I J	K L
	9	Oct 28 1998	2	- é 	_ <u> </u> _	<u> </u>	Ĺ. J.	1 2-	↓ _ ¦.
	I 11	Oct 17 1998	3 -	++		_ _	\sqcup	++	1-1
L Stephan J. Szyszkoski	, in a field survey on .	19 do hereby state that u	ınder 4	-∮	-		10-	11-	——! <u>2</u>
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in- conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Burseu of Land Management or by a decree of a Court of Law and for that the corner points mantioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan			of the 5	18	-17	-16-	15-	14	13
Board of Land Surveyors or by recovered, found as expressed be		f Law; established, re-established, monumer	nted, 7	19	-20-	_21_	_22_	23	21-
NOTE: Not more than 2 com on this certificate.	ters, all in the same towr	n and range, may be recorded	9 10	30	_29	 28	27_	26	254
			11-	-31	_32	_33	_34_	35	-36
A Description of original mo	nument and accessor	se and/or subsequent rectoration:	13	Ш.				1.1.	

(III) Corner common to Sections 26-27-34-35. Established in 1849 by John Burt: North between 34 & 35...80.00 Set Cedar post corner of sections 26,27,34 & 35. Hemlock 18 N24W 42. Hemlock 12 S50E 10."

(9-Sec. 25) East 1/16 corner Section 25. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(III) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner by double proportionate measurement to the original record between monumented corners 79.7193 ch. northerly, 79.7791 ch. easterly, 79.7165 ch. southerly, and 79.7790 ch. mesterly. At the position for the corner I placed a 1"IDx32" iron pipe capped with a 4° dia. cast aluminum MDNR tablet, appropriately stamped, set firm in a mound of rock and portland cement concrete. Corner placed and witnessed by D.Lampela and B.Wheeler, Baraga District Office.

(9-Sec. 25) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between Center of Section 1328.58' west and Quarter corner 1328.58' east. At the position for the corner, which falls on a rock outcrop, I chisel an "x", and erect above it a 1" ID x 32" iron pipe capped with a 4" dia. cast aluminum MDHR tablet, appropriately stamped, made firm in a mound of rock 5' long by 3' wide by 2.5' high. Corner placed and witnessed by 8.Nheeler and D.Lampela, Baraga District Office.

C. Description of monument for corner and a	ccessories established to perpetuate locating the p (9) Chiselled "x" and 1" pipe with 4"	oution of the corner
	(a) currented x sug 1 bibe with 4	OF MANAGEMENT
Blazed and scribed the following:	MDNR cap. Blazed and scribed the	A CHILD
4" Spruce M33E 81.55' "\$26 MBT"	following bearing trees:	15
5" Aspen \$84E 31.05' "S35 MBT"	8° triple W.Birch \$73W 68.65° 1/165 BT	* STEPHAN J.
3" Aspen \$34E 43.3' "\$35 NBT"	10" Balsam S69E 21.1' do	SZYSZKOSKI
2" Aspen S80W 15.3' "X X"	5° Balsam MS3E 54.7' do	LAND *
Placed a squared cedar post SSBE 2.6'.	5" twin Maple M20E 45.15' do	SURVEYOR
Bearings are magnetic. Distances are	Cedar post adjacent in the rock wound.	33986
measured on the slope and are to a notch	Bearings are magnetic. Distances are to	00000
in the lower blaze.	notch in lower blaze.	AND
11-1 1 /	' / /	- / /

Surveyor's Michigan License No.

For the Michigan Department of Natural Resources - Forest Management Division