LAND CORNER RECORDATION CERTIFICATE FILE - D. ----- --- -- 4 A -4 74 A M-L D A 4070

For corners in	U F107	ig requiement of ret 14, back	i. F.M. Teri	•					
Dickinson (Courty)	Located in:	Corner Code #							
1. Public Land Survey	T R								
Property Controlling in Section Miscellaneous Property In Sec.	T_R S T_R S T_R S T_R S T_R			Registi	er of De	ede Sta	ımp &	File Nu	ımber
4. Lot No, Records. Private Claims	rded Plat			1 A B C	: D E	r s	<u> </u>	1 3 M	к <u>г</u>
		Sep 03 1998		3 6	_ [_		_3_		
t, Stephan J. Szyszkoski	, in a field survey on .	, 19 do hereby state er points mentioned in lines 1 and 2 abo	that under	4		-	_10-	11-	12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Lew and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan			tions of the sw and for Michigan	5 -18 -	-17-	_16	_ _15	-14-	-13
Board of Land Surveyors or by recovered, found as expressed by		of Law; established, re-established, mor	numented,	0 -19-	_20_	_2 <u>3</u>	22	23	24-
NOTE: Not more than 2 corr on this certificate.	ners, all in the same tow	m and range, may be recorded		9 - 30-		-28	 _27	26	25
				11 12 31-	-32	-33	_34	35	_36
A Description of original ma	nument and sonessor	ice and/or subsequent restoration:		13[<u> </u>			

(G13) Standard corner common to Sections 33-34 T41M-R29M and Sections 6 T40M-R29M. Corner perpetuated in 1955 by Billy D. Buckler, Ris: " One Cedar stump (possible B.T.) Distance E. & M. checks to good corners. Distance Horth to lake checks. Corner set on edge of lake at high water mark. Corner placed and witnessed July 20, 1955. Corner monument: 1" pipe with 4" brass cap. Mitnesses to corner: 32" White Pine stub M58W 74 links, 8" White Birch 577W 24 links." LCRC dated January, 1962 by Billy O. Buckler says that "+" chisled on rock at G12 is 40.00 ch. north of this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(GI3) Recovered the 1955 monument, a 1" iron pipe capped with a 4" dia. brass Michigan Dept. of Conservation tablet, found encased in a monument of concrete, 4° dia., formed by a concrete filled 4° ID concrete pipe of unknown length, with 6° bell, in good condition, projecting approximately 1 foot. No trace remains of the B.T. cedar noted in the 1955 record or of the two 1955 MBT's. Distance east to a Michigan Dept. of Conservation monument is 2651.35' and north to a "+" chiseled at 612 is 2636.48'. I accept the position of the monument as being the 1955 position and the best available evidence of the position of the original corner. Left the monument in place and marked new mitnesses as described below. Recovered and remitnessed by D.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate	A E M .
(613) Found 1" pipe with 4" brass cap	The state of the s
set in concrete monument. Blazed and	
scribed the following:	STEPHAN J.
4" Maple W14E 41.7' "S34 W8T"	* SZYSZKOSKI
6" Sugar N40M 24.3' "S33 NBT"	* LAND *
13" double Sugar \$44% 56.6'(slope) to	SURVEYOR
nail and DMR washer.	No.
\$69W 96.5' to NE cor. of most M'ly camp	33986
bldg. on E.shore lake. Placed cedar	410 80
post adjacent. Brgs. are magnetic.	William Control of the Control of th
Shoreline is 15' East.	1 /
Signed by Stiphen J. Vyaffresti	Date 3/30/99
Surveyor's Michigan License No. 33986	