MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD 42 M R 27 W T 43 M NR 27 W

Dickinson

DESCRIPTION	OF	CORNER	Section corner common to sections 32 and 33, T43H R27W and sections 4 and 5, T42H R27W
DESCRIPTION	OF	CORNER	MONUMENT 1" pipe and 4" brass cap
WITTNESSES	то	CORNER	Cedar 14 # # 80 # 49 links
			Cedar 12" W 86 W 51 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 2 original cedar bearing trees, 1 still green. Scribe marks very plain on both trees-

Corner was found while cruising timber in this area-

Corner was placed and witnessed on 21 May 1956

SURVEYORS SEAL

REGISTERED LAND SURVEYOR