

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

42 N 28 W
T. 43. NR 28 W. . .

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER ~~Section Corner common to Sections 4, 5, 32, 33 on~~
~~North boundary of township.~~

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap. -----

WITNESSES TO CORNER 6" Cedar N 66° E 58 links -----

5" Cedar S 88° W 17 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced Section Corner 4 and 5 on North boundary of township from
original B.T.'s.

One Cedar B.T. good condition.

One Tamarack Stp. in proper place, very poor condition.

This Section Corner shown to us by H. S. Peterson, District Forester
~~near B.T.'s.~~

Corner placed and witnessed July 18, 1955.



SURVEYORS SEAL

SIGNED Billy D. Buckley DATE 2/27/56
REGISTERED LAND SURVEYOR