LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(DICKINSON COUNTY)		
FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY T. 41 N., R. 29 W.	#C-13 & D-13	
2. PROPERTY CONTROLL- 32 ,T. 41 N. R. 29 K.	#15	
3. MISCELLANEOUS N. E. PROPERTY IN SECTION T. T. S., R. W.		
4. LOT NO, RECORDED PLAT		
5. PRIVATE CLAIMS	REGI	STER OF DEEDS STAMP AND FILING NUMBER
I, Arthur O. Enger do hereby ce	rtify that under requirements of PA	74. Michigan P.A. of 1970.
the corner points mentioned in lines 1 and 2 above were, in a re-established, monumented, re-monumented, recovered or res and rules therefore as required in the current manual of surve Bureau of Land Management or by a decree of a court of law, and 5 above were, in a field survey on, as expressed below and in conformance with the rules of the M Decree of a Court of law:	tored as expressed below and in co y instructions of the United States I Furthermore, that the corner point 19 found, recovered, restored,	nformance with regulations Department of the Interior, is mentioned in lines 3, 4 established or re-established
A. Description of original monument and accessories and/or s	haranak matanatian.	
Found a 1" I.D. x 48" iron pipe with 4" is on 5-13-60 and witnessed by him with a So 35 lks. Corner D-13 (1/4 cor. on S side Found a 1" I.D. x 48" iron pipe with 4" is as set by B. D. Buckler on 5-31-60 and with and an Aspen 5 N41°W 25 lks., both dead of Sec. 32, T41N, R29W on 4th Corr. Line by approximation subsequently, as there is a B. Description of corner evidence found and/or method applied.	P, T41N, R29W on 4th Corrected to the Corrected State of Sec. 32, T41N, R29W or crass cap (bent over, in state of the Corrected State of Sec. 32, T41N, R29W or crass cap (bent over, in state of the Corner 15 (West of the Corner 1	and an Aspen 8 N31°W 4th Corr. Line): 1 low rock mound) Pine 9 N49°E 60 lks. 1/16 cor. on S side ginal survey and only 0 ft. from monument
Corner C-13: Re-witnessed corner on 8-27-79 Buckler's corner record is on file.		
Corner D-13: On 8-28-79 replaced Buckler's as the long pipe was too unstable to supfalls on exposed bedrock.	monument with new monumer port with a reasonable mou	nts shown below, and of rocks. Corner
Corner 15: Established 8-27-79 on 4th Correstd. Sec. Cor. 19.8675 ch. W and Std. 1/4	ection line, proportionate 4 cor. 19.8675 ch. E.	ely on line between
C. Description of monument for corner and accessories establed Corner C-13: Monument and NBT's as set by Red Maple 5 S86°W (mag.) 38.8 Corner D-13: Cap set over it in a mound of Red Maple 8 S45°E (mag.) 25.2 Red Maple 5 N82°W (mag.) 8.0	Buckler. Declination 10 1 ft. "S2, NBT" (Enger) 1" I.D. x 24" iron pipe v rocks. ft. "1/4S, NBT"	35' West.
Declination 3° 35' West. Corner 15: 1" I.D. x 24" iron pipe with 3 Red Maple 6 N42°E (mag.) 41.7 f Cedar 9 N55°W (mag.) 26.8 f Declination 3° 20':West.	t. "1/16S, BT"	rock mound.
SIGNED BY	DATE	
		(SEAL)
SURVEYOR'S MICHIGAN REGISTRATION NO		
FOR STATE AND UNITED STATES AGENCIES:		State of the state
SIGNED BYCHIEF OF SURVEY PARTY	DATE.	
APPROVED AND SIGNED BY MICHIGAN REGISTERED LA Arthur O. Eng	DATE DATE	AMEAL)
Michigan Department of Natu	ral Resources	The state of the s
SURVEYOR'S MICHIGAN REGISTRATION NO. 13		William Committee