

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ⁴³ NR 27 W

Dickinson

----- COUNTY

DESCRIPTION OF CORNER Section corner common to sections 21, 22, 27 and 28

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Tamarack 8" S 81 W 55 links

Tamarack 4" N 62 E 18 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 2 original tamarack bearing trees, 1 in good condition and 1 in poor condition. Found 3 old stake points in muck under moss at point where corner fell.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 21 May 1956

SURVEYORS SEAL

Henry S. Peterson

SIGNED

Henry S. Peterson

REGISTERED LAND SURVEYOR

DATE

5/25/56