## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.43 NR 28 W

			D	ickinson	COUNT
DESCRIPTION	OF	CORNER	Section corner co	mmon to sections 15,3	16,21 and 22
DESCRIPTION	OF	CORNER	MONUMENT_1" pi	pe with 4" brass cap	P
WITTNESSES	то	CORNER	Cedar 13" N	81 E 26 links	
			marked <b>3 1</b> 5	nb <b>t</b>	
			White Birch	10" S 81 W 25 links	· - <b></b>
			marked S 21	n <b>bt</b>	

Distances measured from notch to center of brass cap.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was found while cruising timber in this area.

Corner was replaced from cedar original bearing tree in fair condition. Stump in place. Found scribe marks on part of "BT" face. Other bearing tree (original) has cedar stump bottom in place with no identifying marks.

Corner had been previously perpetuated by Mm. C. Johnson, Dickinson County Engineer.

Corner was placed and witnessed on 23 January 1957 with Clarence Ryberg.

SURVEYOR'S SEAL

Henry S.Peterson

-- L

1/2 /57

REGISTERED LAND SURVEYOR