MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 43 N NR 29 W

			Dickinson				COUNT	COUNT	
DESCRIPTION	OF CORNER 1/4 corner between sections 30 and 31 OF CORNER MONUMENT 1" pipe with 4" brass cap								
DESCRIPTION	OF	CORNER	MONUMENT						
WIT TNESSES	то	CORNER		Tamarack	11"	_ S 4T W	55 1/2 links		
				Aspen	8"	S 57 E	9 links		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original cedar bearing tree in fair condition. Tree is in place but down. Screbe marks are plain.

Corner had been previously perpetuated by unknown surveyor. Old wood post in place.

Corner found while cruising timber in this area with Norman Karstent

Corner was placed and witnessed on 5 June 1956

SURVEYOR'S SEAL

Henry b. Feleson

Henry S. Peterson DATE 6/6/56
REGISTERED LAND SURVEYOR