LAND CORNER RECORDATION CERTIFICATE

	Filing	g Requirement of Act	74, Mich. P.A. 197	70	
For corners in	·	-	ı		
Dickinson	Located In:	Corner Code #			
(County)					
1. Public Land Survey	T <u>44#</u> R_ T <u>44#</u> R_ TR		-		
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR		-	Register of Deeds Stamp & File Num	nber
4. Lot No, Recor 5. Private Claims	ded Plat			A B C D E F G H I J K	L M
		Jun 14 2001	•	2 6 5 4 3 2	-i-
, Stephan J. Szyszkoski	in a field evenue on		nereby state that under	4 - 7 - 8 - 9 - 10 - 11	_12_
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the I that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	in P.A. of 1970, the come rules therefore as require nterior, Bureau of Land M in lines 3, 4 and 5 above a Decree of a Court of	er points mentioned in lines of the current manual of substance of the current or by a decree of the conformance with the	1 and 2 above were in rvey instructions of the a Court of Law and /or a rules of the Michigan	5	-13 -24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			ded	9 - - - - - - - - -	
on this certificate.				10 30 29 28 27 26	-25
				12 31 32 33 34 35	-36-
(M5) Corner common to Section established by proportionate	s 12-13 T44N-R27M and measurement by forest	1 7-18 T44N-R26W. Reest try division Survey cre	tablished in 1950 by w while working in t	Spruce M34E 52 links, 8" Elm M32W 22 link y Dean C. DeLaMater RLS: "This corner was this area. One probable B.T. still in S3W 23 links, 14" Spruce M80W 63 links."	.
B. Description of corner evid	dence found and/or mo	ethod applied in restoring	or reestablishing corr	ner.	
(All) Recovered the 1953 mon Elm, now down and decaying. new witnesses as described be	nument as described, i No evidence of the s Now.	in good condition, and pruce was found - it wo	at record bearing ar uld fall in a clear-	nd distance from the remaining 1953 with -cut. Left the monument in place and mad	de
(M5) Recovered the 1950 monum SE and MW spruce witnesses, t and tam. post point at corner	ooth down but with sc	ribing visible. The S₩	spruce is not evide	distance from the decaying remains of t lent. Also found old decaying spruce pos ribed below.	ne t
7" Balsam N81E 2.5' 7" Poplar S53W 10.2' 4" W.Spruce N39W 3.0'	ith 4" brass (M i: MD 'S30 NBT" 5" 'S30 NBT" 6" 'S36 NBT" 7" 'S25 NBT" 6" earings are Sq notch in ma	ories established to perpe 5) Found 1"ID iron pipe 0C cap. Blazed and scr 8.Spruce N28E 19.7' B.Spruce S47E 18.6' 8.Spruce S32M 26.1' 8.Spruce N32M 29.0' 'd cedar post adjacent. gnetic. Distances are wer blaze.	with 4 brass ibed:	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	
Signed by Stepha	d. Ins	hosh:	Date	8/8/01	

Surveyor's Michigan License No.