LAND CORNER RECORDATION CERTIFICATE Siling Despitement of Act 74 Lich DA 1070

	1 1001/2	I todanomonica i i i	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
For corners in Dickinson	Located in:	Corner Code #					
(County)	Lyonou III.						
1. Public Land Survey	T44N R 2 T44N R 2 T R	71 J1					
Property Controlling In Section Mecellaneous Property in Sec.	TR S TR S TR S TR				of Deeds S		
4. Lot No, Reco 5. Private Claims			_	1 A B C 2 6 3	D E F	G H I	* +
. Stanhan J. Szyszkoski	-	lun 19 1997 10 de bereb	e alain that under		- 8 9	10-1-1	112_
Stephan J. Szyszkoski requirements of P.A. 74, Michig conformance with regulations an United States Department of the that the corner points mentiones Board of Land Surveyore or b	d ruise therefore as required Interior, Bureau of Land Mar II in lines 3. 4 and 5 above w	in the current menual of survey i negement or by a decree of a Co we in conformance with the rule	metructions of the urt of Law and for is of the Michigan	5 -18 7	17 -16-	151	6-13-
recovered, found as expressed b	elow:			8 -19-	-2021	 2/2 - 2	3 24
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.			10 30	-2928	272	6-25-	
				11 12 31	-3233	34 -3	536

A. Description of original monument and accessories and/or subsequent restoration:

(L1) Quarter corner common to Section 1 744M-R2BM and Section 36 T45M-R2BM. Corner remonumented by Billy D. Buckler, RLS in 1959: "This corner was replaced from one cedar B.T. bearing M20M 08 links. 8.T. in fair condition. Stump out 2 1/2' high. Corner found by Forestry Division Survey Crew while running County line". Set 1" Pipe with 4" Brass Cap. 6" Aspen M39E 35.5 links, 14" Aspen M70M 25

(JI) Quarter corner common to Section 2 T44N-R28W and Section 35 T45N-R28W. Corner reestablished in 1959 by Billy D. Buckler, RLS: "This corner was re-established by proportionate measures by two Section corners. No evidence of original corner". Buckler set a l" pipe with 4° brass cap and marked the following: 18° R.Pine M23M 285 links, 22° R.Pine S65M 300 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(L1) Recovered the 1959 monument, as described, the cap being a cast Michigan Dept. of Conservation Forestry Division tablet, at record bearing and distance from the remains of the 1959 witnesses, now both dead and down. Scribing still visible on the aspen remains. Left the monument in place and marked 4 new witnesses as described below. Corner recovered and rewitnessed by B.Wheeler and D.Lampela, Saraga district Office, MDHR. No measurements to other corners were made at this time. This corner is being rerecorded in order to update the accessories.

(J1) Found the 1959 monument as described, the cap being a cast brass Michigan Dept. of Conservation Forestry Division tablet, in good condition, at record bearing and distance from the 1959 witnesses, both in good condition. Left the monument in place and marked two new accessories as described below. Corner is located in a small clearing approx. 200' (paced) south of E-M trail road. Corner recovered and remitnessed by D.Lampela and B.Mheeler, Baraga District Office, MDMR. Ho measurements to other corners were made at this time. This corner is being rerecorded in order to update the accessories.

C. Description of monument for corner and accessories established to perpetuate locating the position of the
--

	colude and accessouse ascessed to bethermare located me bossou of me.	COITIOI.
(LI) Found I pipe with 4" brass c	ap. (Ji) found i" pipe with 4" brass cap.	2 37 27
Blazed and scribed the following:	The 1959 witnesses:	
9" Red Maple M62N 15.6' 1/4S N	BT" 24" R.Pine N18W 285 links	STEPHAN J.
5" B.Ash \$77W 18.2" "1/45 N	BT" 28" R.Pine 570W 300 links	SZYSZKOSKI
5" B.Ash \$60E 19.1" "1/45 N	BT" Blazed and scribed the following:	LAND
7" Twin B.Ash N62E 21.5" "1/45 N	BT" 5" White Pine \$87W 71.5' "1/45 MBT"	
Bearings are magnetic.	4" R.Pine N48E 59.1' "1/4S N8T"	SZIRVEYOR
•	Placed a 3° squared post adjacent.	33986 No.
•	Bearings are magnetic.	00000
		CAND SO

Surveyor's Michigan License No.

For the Michigan Department of Natural Resources - Forest Management Division