LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in Dickinson | Located in: | Comer Code =## |
|-----------------------------|--------------------|--|
| (County) | | |
| 1. Public Land Surve | y T 448 R 290 | <u> 11 </u> |
| | Ť A | |
| | T A | |
| | ' T R | |
| 2. Property Controlli | ng S 2 T 44N R 29N | |
| in Section | S T R | |
| 3 Miscellaneous | S T R | |

Property in Sec.

Register of Deeds Stamp & File Number

| 4. | Lot No | , Recorded Plat | |
|----|----------------|-----------------|--|
| 5. | Private Claims | | |

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in times 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lew and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11) Corner common to Sections 2-3 T44H-R29H and 34-35 T45H-R29H. Corner remonumented by single proportionate measurement in 1961 by Billy B. Buckler. 1° Pipe with 4° brass cap. 1961 NBTs were 9° J. Pine N70E 14 links, 10° J. Pine S10E 62 links, 9° J. Pine S45H 103 links. Found no subsequent record.

(3-Sec. 2) North 1/16 corner between Sections 2-3. Corner monumented in 1965 by Billy D. Buckler, RLS. 1° pipe with 4° aluminum cap. 9° Jack Pine M65M 37 links, 8° Jack Pine S71E 19 links. Found no subsequent record.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

(II) Found the 1961 monument, in good condition, at record bearing and distance from the 1961 MRTs: J. Pine ME is dead, J. Pine SE is now a stump, J. Pine SH in good condition (1994 mag. bearing is \$40M). Left the monument as found and marked two additional witnesses as described below.

(3-Sec. 2) Found the 1965 monument, as described, in good condition, at record bearing and distance from the 1965 BTs: the Jack Fine No in good condition, the Jack Fine SE now a stump. Left the monument as found and marked three new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

([1]) Found 1" pipe with 4" brass cap.

([3]) Found 1" pipe with 4" alue, cap.

[Blazed and seribed the following saw.

(II) Found 1" pipq with 4" brass cap. Blazed and scribed the following new bearing trees: 8" J. Pine HSSE 35.1" "SSS HBT" (3) Found 1" pipe with 4" alum, cap.
Blazed and scribed the following bearing
trees:
4" Balsam M63E 26.3" "1/165 MBT"
3" J. Pine 549E 45.8" "1/165 MBT"

STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986

10" Aspen N30N 44.0" "S34 MBT" 3" J. Pine S49E 45.0" Dearings are magnetic. 4" J. Pine S34N 45.0"

Bearings are magnetic.

Date 9-21-94

"1/163 NBT"

33986

PRINT APPROVES BY MICHIGAN STATE BRANG OF LAND SURVEYORS, AMI. 29, 1871