

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T44 & 45 NR 29 & 30 W

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 36, 31, 6, 1 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER No witnesses available -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner. Two Pine stps. in proper position, badly burned.

1 1/2" pipe has been placed by unknown surveyor.

Section Corner found by Forestry Division Survey Crew while making a partial re-survey of this area.

Section Corner located on N. W. slope of hill.

Trail road N-S is 3 chs. West.

Corner placed and witnessed May 11, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buchler
REGISTERED LAND SURVEYOR

DATE 5/14/56