MICHIGAN JAN 20 1953

DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T. W NR 30 W

DESCRIPTION	OF	CORNER	Section corner commente sections 27,26,33 and 34
DESCRIPTION	OF	CORNER	MONUMENT 18 pipe with 48 brass cap
WIT TNESSES	то	CORNER	Hemleck 20 H 03 W 182 links
			No other new bearing trees available.
-			

RESTORED.

This corner was replaced from original sprace bearing tree in fair condition. Corner was found while cruising timber in this area.

Corner had been previously perpetuated by unknown surveyor. thermer was placed and witnessed on 16 January 1956.