SURVEY & REMONUMENTATION

APR 2 7 1995

94 OCT 26 AM 8: 57

	- " "		\sim	ION
\sim		٠л١	-	16 3156
1 1 1	111/11	\ //! {		

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

OOMinio	Filing Require	ement of Act 74, Mich. P.A. 1	
For corners in		·	REGISTER OF DEEDS
EATON	Located In:	Corner Code ##	EATON COUNTY, MICH.
HAMLIN TOWNSHIP 1. Public Land Survey	T _1.N_ R _3W_ T R T R T R	B_5	
in Section S 3. Miscellaneous S	T R		LIBER 3 PAGE 473 Register of Deeds Stamp & File Number
4. Lot No, Recor 5. Private Claims			A B C D E F G H J J K L M
I, <u>David Clifford</u> in a do hereby certify that under requirem in lines 1 and 2 above were in confourrent manual of survey instruction Management or by a decree of a Cou above were in conformance with the Court of Law; established, re-established below:	nents of P.A. 74, Michigan P.A. formance with regulations and is of the United States Depart it of Law and/or that the corner rules of the Michigan Board o	of 1970, the corner points mentioned drules therefore as required in the ment of the Interior, Bureau of Land r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a	5 6 -18 -17 -16 -15 -14 -13 - 7 8 -19 -20 -21 -22 -23 -24 - 9 10 -30 -29 -28 -27 -26 -25 -
NOTE: Not more than 4 corner on this certificate.	s, all in the same town an		11 12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1. Original Post set by Hervey Parke D.S. in Jan. 1826 B. Ash 9 S 15 E 7 Do 6 N 3 E 6 3 E 6
 - 2. W.H. Bailey Co. Surveyor set an iron stake for the cor. in a survey recorded in Vol. 2 page 111 in Feb. 1884 NBT Hick. 2" N37W 96 lks

(OVER)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:...., Searched at apparent location of corner and found ½" Bar and Cap #18988 (D. Fluke). Extracted Bar & Cap and found 3/4" Pipe beneath it. Extracted 3/4" pipe (6" long) and dug 4'X4' Hole into natural Ground(Dry Black Muck). Found nothing more(Its a wonder the road is still there). Found 12" Hick. Stump N35°W 63.4'(1884 Witness). Accepted 3/4" pipe as perpetuation of corner and replaced with Standard 3/4" Bar & PA 345 Cap. Measured North 2655.59 to B-4,

Accepted 3/4" pipe as perpetuation of corner and replaced with Standard 3/4" Bar & PA 345 Cap. Measured North 2655.59 to B-4, East 2656.86 to C-5, West 2622.24 to A-5.

DAVID L. CLIFFORD LAND SURVEYOR SURVEYOR NO. 25837

Standard 3/4" Bar & PA 345 Cap PS 25837 Centerline Nye Highway & LAND Kikendall Road

Found Accolade Nail & Tag in E. Side 10" Maple NAZ 358° 29.20' Set Nail & Tag # 25837 in E. Side 28" Dbl. Maple NAZ 349° 85.75' Set Nail & Tag # 25837 in E. Side 14" Maple NAZ 300° 76.82' Set Nail & Tag # 25837 in W. Side Power Pole NAZ 221° 71.85'

Apres all		
Signed by	Date	July 26,1994
Surveyor's Michigan License No25837		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 £.

3. Ronnie Lester LS # 18998 recorded corner in Jan. 1973 in Liber 1 of Corners page 197 as a found 1" pipe in centerline Nye and Kikendall Highways

Set Nail & Tag W. Side 28" Maple SW 64.54'
Set Nail & Tag E. Side 10" Maple North 19.32'
Set Nail & Tag SE Side 14" Maple NE 25.31'

a i da Pomi

acrition C.I.