OCT 1 6 1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

IRFR.	BER 3	PAKE	9149
-/ /5 & / C	\sim	PRE	KIK

For corners in	Filing Require	ment of Act 14, Mich. P	FILED
EATON COUNTY	Located In:	Corner Code ##	Copy
Brookfield Township 1. Public Land Survey	T R 4W T R T R	C-7	93 OCT -7 AM 9:
in Section S	T R S T R S T R		LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY, MICH Register of Deeds Stamp & File Number
 :	S T R		Tieglote: 6. 50000 Grainp & Fire Hallison
4. Lot No , Reco	orded Plat		ABCDEFGHIJKL
5 Private Claims			

I. <u>David R. Lohr</u>, in a field survey on <u>July 31</u>, 19 <u>93</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- C-7:/Post set by Sylvester Sibley in 1825. Witnessed by: Tamarack 9" S2 1/2°E 19 links, Tamarack 9" N81°W 23 links.
 - 2. Marginal Note in Rd. Comm. copy GLO notes, page 163 by Harvey A. Williams in 1917 & 1918 Indicates two stakes witnessed by Anchor post S45 1/2°E 36'; Anchor post N46 1/2°E 35'; Anchor post N45 3/4°W 35'
 - 3. No other record found of subsequent surveys in County Surveyors Records.

(OVER)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- C-7 Excavated area of 1/2" iron. Found that iron was imbedded in 6" cedar post with stones and plow point about 8" deep. Also encountered remains of Corduroy Road bed at 8" depth.

This post is accepted as a careful and faithful perpetuation of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C-7 Replaced 1/2 iron with 3/4" x 24" Remonumentation pin and cap in center of wood post.

Witnessed by: Set nail and tag #30090, SE/S of 12" Poplar Set nail and tag #30090, NE/S of 10" Boxelder 63° 82.03' 134° 83.701 Az. Set nail and tag #30090, W/S of 32" Poplar 159° 81.72' ۸z. Set nail and tag #30090, E/S of 10" Elm Set nail and tag #30090, SW/S of 6" Poplar 192° 109.28' Az. 314° 70.10' Az.

Signed by Aurel D. John
Surveyor's Michigan License No. 30090 P

Date August 9, 1993

VICTORTY

OF MICHIG

DAVID R. LOHR

PROFESSIONAL

Ng 30099,

AROFESSION

P.A. 345 EATON COME FORM APPROVED BY MICHIGAN STATE

PEER APPROVED 8/25/93 M

10/18/93.

(Continued)

C-7:

RLS#25832
6.Corner found by Larry Bryan on April 8, 1983 recorded Liber 2, page 945.
Found 1/2" iron in centerline Mahan and Sherman Roads. Witnessed by:

Fd. nail NE side utility pole, S45°E, 56.25' Fd. nail South side 6" Poplar, N60°E, 78.90'

(Gone)

Fd. nail North side, R.R. tie corner post, S45°W, 48.87°

(Gone)

All above witnesses missing.

4. Certificate of survey by Robert Reed, Liber 2, Page 522, indicates iron pipe raised with 10" spike witnessed by: RR track set vertical SE 36.50'
RR tie post NW 27.75'

Rd sign post

SW 31.50'

5. CORNER REFERENCED IN SURVEY BY ROBERT REED, LS #19004, ON FEBRUARY 1, 1978, RECORDED IN LIBER 2, PAGE 522. REED HAS REPORTED THAT HE MEASURED NORTH TO C-6 A DISTANCE OF 2644.65' AND 5289.30' TO C-5.

- 7. CORNER USED IN TRAVERSE FOR SURVEY BY LARRY BRYAN, DATED APRIL 8, 1983, RECORDED IN LIBER 3, PAGE 567. TRAVERSE COMP. SHEET SHOWS DISTANCE TO C-8 AS 2649.35' AND DISTANCE TO C-9 AS 5298.70'
- 8. SURVEYOR'S RECORDS REVEAL NO ADDITIONAL DATA.