copy

		LAND CORN	IER RECORDATION CER	TIFICATE P.A. 1970 0CT 30 PM 1: 47	
For corners is	n	Filing Requi	rement of Act 74, Mich.	P.A. 1978 DULI 30 PM 1: 47	
EATON		Located In:	Corner Code ≠≠		
10	County)	Eodaled III.	Comer Code ++	LINDA M. TWITCHELL REGISTER OF DEEDS	
WALTON TOU 1. Public La		T 1N R 5W	<u>M-8</u>	EATON COUNTY, MICH	
	•	T R			
		TR			iaa =
2. Property	Controllina S	' # T R		Liber 3 pg.	734
in Section	n S_	T R		Libo PJ	
3. Miscellan	ieous S_	T R		Register of Deeds Stamp & F	ile Number
Property i	in Sec. S_	TR			
					ніјкі
5. Prívate Cl	laims				
				3	3 - 2 - 1 -
				4 7 8 9 9	01112
I. <u>DAVID R.</u>	<u></u>	field survey on OCT.	107 , 19 <u>94</u> A of 1970, the corner points men	tioned 5	
in lines 1 and :	2 above were in confo	ormance with regulations a	ind rules, therefore as required	in the 18 17 16 16 1	51413
Current manual Management or	l of survey instructions r by a decree of a Court	s of the United States Depa of Law and/or that the corr	urtment of the Interior, Bureau o er points mentioned in lines 3, 4	tLand 7 and 5 8 13 20 21	
above were in o	conformance with the r	ules of the Michigan Board	of Land Surveyors or by a Decr	ee of a	23 24
expressed belo		olistiea, monumentea, re	-monumented, recovered, fou	10	72625
NOTE: Not r	more than 4 corners	s, all in the same town a	and range, may be recorded	11	
on th	nis certificate.			12 31 32 33 3	3536
A. Description	on of original monur	nent and accessories ar	nd/or subsequent restoratio	13 <u> </u>	
			.S. DEP. SURVEYOR I		
		BY: BEECH 16" S	16° W 42 lks (2	7.72')	
		BEECH 14" N	3° W 15 1ks (7.90')	
	2. NO OTHER R	EFERENCES FOUND I	N COUNTY SURVEYORS	RECORDS.	
		CONTINUED 0	N BACK		
B. Description	on of corner evidenc	e found and/or method	applied in restoring or rees	tablishing corner:	
M-8:	FOUND PIPE IN			ROAD AND 3.5 FT. WEST DETERMINED THAT CORNER	
			NE. MEASURED NORTH	TO M-7 A DISTANCE OF	
	2647.08 FT. A	AND SOUTH 2647.06	FT. TO M-9. DID NO	OT EXCAVATE INTERIOR OF	
				IN 1975. ACCEPTED PIPE ACE IN MON. BOX AND	
		5 CAP #30090 ON P		THE IN HON. BOX HIND	
C. Descriptio	on of monument for	corner and accessories	established to perpetuate I	ocating the position of the corner:	
m-8:		A 345 CAP #30090			Market .
	WITNESSED BY:			SATE OF MIC	HICA
	SET N&T 30090		AZ. 24° 275.43'	* DAVID R	1.4
	SET N&T 30090 SET N&T 30090		AZ. 124° 149.80' AZ. 324° 72.65'	₹ LOHR	*
	A-8 BROOKFIEL		AZ. 180 44.32'	PROFESSION SURVEYO	R OF

AR OFESSIONAL STREET P.A. 345 EATON COUNTY FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

PEER APPROVED 9/26/96 MC

REVISED JAN., 1983 Surveyor's Michigan License No. _____30090_

1 7. 1

Page Z

M-8: PART A - CONTINUED

3. CORNER RESET BY RICHARD STEADMAN ON SEPT. 4, 1975 AND REFERENCED IN LCRC DATED SEPT. 12, 1975 AND RECORDED IN LIBER 2, PG. 311.
"DUG HOLE IN THE INTERSECTION OF COCHRAN AND MILLER HWY., BUT FOUND NOTHING. I CONCLUDED THAT THE CORNER WAS LOST AND RESET IT BY SINGLE PROPORTIONATE MEASURE."

"SET 1/2 IRON PIPE AND MONUMENT BOX TO MARK THE CORNER"
WITNESSED BY: 40" MAPLE N75W 80.18 FT.
TELEPHONE POLE N25W 65.53 FT.
2" DIA. STEEL SIGN POST \$42W 37.30 FT.

- 4. CORNER REFERENCED IN UNRECORDED MORTGAGE REPORT BY K. DON FLUKE, RLS #18988, DATED JULY 20, 1981, JOB NUMBER 227. MORTGAGE REPORT SHOWS DISTANCE BETWEEN M-8 AND M-7 OF 2646.96 FT.
- 5. NO OTHER REFERENCES FOUND.