LAND CORNER RECORDATION CERTIFICATE

		•	5/	
uı.	## FM	O	AM 11:	27.0
ブサ	JUN	••• 4	- AM 11:	54
		•	1411 E E .	~4

EATON TOWNSHIP For corners in	Filing Requ	uirement of Act 74, Mich.	P.A. 1970		•	,	
EATON County)	Located In:	Corner Code ##	[_	INDA M. 7 REGISTER EATON CO	WITCH OF DEE	ELL EDS	
1. Public Land Survey	T2N R4W T R T R T R	L-9	<u></u>	IBER 3		44°	4
Property Controlling in Section	S T R S	FON FON			J	,,,,	
Miscellaneous Property in Sec.	S T R	HELSEL LAND LANE SURVEYOR CONTROL	Register	of Deeds S	itamp &	File Nur	nber
4. Lot No, Re 5. Private Claims	corded Plat	No. 15994	2 3	B C D	E F G	H I J	K L
I, Ron Helsel, do hereby certify that under require lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a above were in conformance with Court of Law; established, reexpressed below:	uirements of P.A. 74, Michigan P conformance with regulations ctions of the United States Der Court of Law and/or that the co n the rules of the Michigan Boar	P.A. of 1970, the corner points ment and rules therefore as required partment of the Interior, Bureau former points mentioned in lines 3, and of Land Surveyors or by a Dec	I in the of Land 7 4 and 5 8 ree of a	-18 -17 -19 -20 -3029	21 28	-101 -151 -222	3
NOTE: Not more than 4 co on this certificate.	rners, all in the same town	and range, may be recorde	d 11	-31 -32	33	-343	53

A. Description of original monument and accessories and/or subsequent restoration:

GLO record indicates "West corrected between Sections 24 and 25. 39.67 set post at average on true line. Lynn 13" S51 1/2 E 34; and Beech 16" N68W 12". Sylvester Sibley November 1825. No County record of this corner located.

Oscar Boss, LS #13574 recorded corner per P.A. 74 in Liber 2, Page 98 on February 20, 1974. LCRC indicates "1/2" iron Found" with witnesses: South 33.02' 1/2" iron found; North 26.96' fence post N.E.S.; S 75° W 88.70 Nail N/S SEE OTHER SIDE DOCUMENT power pole.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Field notes of R. Lester, PS #18998, dated 8/17/1993 indicates the following: "Investigation at this site revealed a 1/2" iron bar 3' South of centerline of Long Road (gravel) on occupation line to North. Excavated 3' diameter hole to depth of 1.5 feet to natural ground. Found nothing but dirt. Set 1/2" bar and identification cap at location of found 1/2" bar and witnessed. Location falls on old occupation line to North and matches deed and survey lines East and West. The 1/2" bar as found is in the location as set by Boss on LCRC in Liber 2, Page 98. Found his nail and tag on East side of old fence post now lying down to North at correct distance and it also matches location of corner as I found it in 1979. I believe this is to be the perpetuated location of SEE OTHER SIDE OF DOCUMENT the corner L-9 by common accord."

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1/4 corner Section 24, T2N, R4W. Set 3/4" x 24" steel bar and cap. Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" on South side 24" apple, N78°W, 124.29' Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" North side utility pole, S78°W, 88.69' Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" East side 36" oak, N07°E, 54.39' Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" North side utility pole, S75°E, 120.46'

Signed by Son Hel	sel	Date	March	25,	1994	·	:
Surveyor's Michigan License No. P.A. 345 EATON COUNTY PEER APPROVED 5/25/94			FORM APPROVED BY	MICHIGAN	t STATE BOARD OF	F LAND SURY	VEYORS, JAN. 28, 1 REVISED MAY 14, 1 REVISED JAN., 1

SECTION "A" OF L-9, T2N, R4W, continued

Various surveys per P.A. 132 of 1970 recorded.

Liber 1, Page 568, December 17, 1973; O. Boss LS #13574. Witnesses same as on P.A. 74 form Recorded Liber 2, Page 98.

Liber 1, Page 742, June 6, 1974; L. Hendryx LS #3276. Indicates corner but no witnesses given.

Liber 2, Page 49, December 3, 1975; R. Lester LS #18998. Witnesses same as on P.A. 74 form recorded Liber 2, Page 98.

Liber 2, Page 98 (same recording numbers as previous LCRC) dated May 26, 1976; 0. Boss LS #13574. Witnesses same as on P.A. 74 form Recorded Liber 2, Page 98.

Liber 2, Page 725, July 20, 1978, L. Hendryx LS #3276. Indicates corner but no witnesses given.

Liber 2, Page 726, July 20, 1978, L. Hendryx LS #3276. Indicates corner but no witnesses given.

Liber 3, Page 85, September 25, 1979, R. Lester LS #18998. Corner identified as 1/2" iron with witnesses: Boss nail and tag in East side fence post, North 26.96'; Boss nail and tag in North side power pole, S75°W, 88.70'; Nail and tag #18998 in South side 12" apple, N80°W, 124.31'; Nail and tag #18998 in South side 6" elm, N50°W, 51.72'

Liber 3, Page 203, August, 1980, A. Williams LS #21275. Indicates corner and witnesses same as on P.A. 74 form recorded Liber 2, Page 98.

Liber 5, Pages 703-704, December 2, 1993, R. Lester LS #18998. Corner identified as 1/2" bar and cap. Witnesses:
Set galvanized nail and 1 1/4" brass tag stamped "LS 18998" on South side 24" apple, 282° az., 124.31'
Set galvanized nail and 1 1/4" brass tag stamped "LS 18998" North side utility pole, 259° az., 88.62'
Set galvanized nail and 1 1/4" brass tag stamped "LS 18998" East side 36" oak, 06° az., 54.40'
Set galvanized nail and 1 1/4" brass tag stamped "LS 18998" North side new utility pole, 106° az., 120.45'

SECTION "B" OF L-9, T2N, R4W, continued

Field investigation on March 17, 1994 revealed a 1/2" bar and cap #18998 2' South centerline of Long Highway on fenceline North. Excavated a 6' x 6' x 2' deep hole around found 1/2" bar and cap #18998. Found no evidence of prior corner monumentation. Accepted 1/2" bar and cap #18998 as perpetuated location of corner and set 3/4" x 24" steel bar and cap #18994 in steel collar. Left following witnesses:

Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" on South side 24" apple, N78°W, 124.29'
Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" North side utility pole, S78°W, 88.69'
Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" East side 36" oak, N07°E, 54.39'
Found galvanized nail and 1 1/4" brass tag stamped "LS 18998" North side utility pole, S75°E, 120.46'