APR 27 1995

LAND CORNER RECORDATION CERTIFICATE

For	corners	COMMISSION
-----	---------	------------

Filing Requirement of Act 74 Mich PA 1970

DAVID 1 **CLIFFORD** LAND prnerSURVEYOR

NO.

REVISED JAK.

THE BUTCH STREET

For corners in				94 NOV 30 AH 9: 11	
EATON (County)	Located In:	Corner Code ##			
CARMEL TOWNSHIP 1. Public Land Survey	T 2N R 5W T R T B T R	K-11		LINDA M. REGISTE EATON C	TWITCHELL R OF DEEDS DUNTY, MICH.
in Section S 3. Miscellaneous S	T R T R R T R R		LIBER 3 Register of Dee	, –	11 ile Number
4. Lot No, Recorded 5. Private Claims			2 A B C	D E F G	H I J K L N
I, D.L. Clifford , in a field of hereby certify that under requirement in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rule Court of Law; established, re-established expressed below:	s of P.A. 74, Michigan P.A. ance with regulations an the United States Depart Law and/or that the corne is of the Michigan Board o	of 1970, the corner points mention of rules therefore as required in 1 tment of the Interior, Bureau of La er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree o	ned 6 18 19 19 10 10 10 10 10 10 10 10 10 10 10 10 10	- 8 - 9 - 1 -17 - 16 - 1 -20 - 21 - 2 -29 - 28 - 2	51413
NOTE: Not more than 4 corners, a on this certificate.	ill in the same town ar	nd range, may be recorded	11 12 31	-32 - 333	4 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- 1. Original Post set by Sylvester Sibley D.S. in Dec. 1825 Beech 18 N88 $\frac{1}{2}$ W 10 12 N 42 E 39 Do
- 2. Oscar Church Co. Surveyor set a stone for the cor. in a survey recorded in Vol. 2 page 46 in Apr. 1877

(OVER)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Searched at apparent location of corner and found 1 Pipe and Cap #11370 4' South of centerline Broadway on East edge of Golf Course drive. Extracted Pipe and found stone beneath it. All of R. Steadmans witnesses are now stumps except for the power pole which is gone. Accepted stone as corner as perpetuated by Oscar Church and replaced pipe with Standard Bar and PA 345 Cap. Set Monument Box.

C. Description of monument for corner and accessories established to perpetuate locating the position of Standard 3/4" Bar & PA 345 Cap PS 25837 4' South of Centerline Broadway in monument box.

A TEND Set Nail & Tag # 25837 in S. Side 36" Maple NAZ 86° 253.55' Set Nail & Tag # 25837 in N. Side 10" Maple NAZ 101° 163.62' Set Nail & Tag # 25837 in N. Side Mult. 6" Cherry NAZ 238° 63.31' Set Nail & Tag # 25837 in S. Side 14" Ash NAZ 280° 191.70' Top most point large boulder NAZ 342° 61.90'

Signed by Danie Office	Date Oct. 25, 1994	
Surveyor's Michigan License No. 25837	FORM APPROVED BY MICHIGAN STATE BOARD OF I	LAND SURVEYORS, JAN. 28, REVISED MAY 14.

3. Eaton County Road Commission Grid Map Boat Spike Fen. Cor. North 34.53' 24" Triple Elm N.E. 53.3'

LIBERS pg 542

4. R. Steadman L.S. 11370 recorded corner in Oct. 1978 in Liber 2 of corners page 573 as a ½" pipe set on top of a pointed stone found under Eaton County Road Comm. Boat spike mentioned in item 3
Twin 6" Wild Cherry S61W 63.84'
Twin 6" Elm S10W 35.62'
8" Elm S70E 108.42'
Power Pole N02E 139.65'

古龙河 计数字符号 医腹腔线

7 NEA 30