FEB 2 2 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

95 NOV 28

. TOUTCHELL

Por comers in		LINDA MA DE DE DE
EATON COUNTY	Located in: CHESTER TOWNSHIP Corner Code #	LINDA M. TWI DEEDS REGISTER OF DEEDS EATON COUNTY, MICH.
1. Public Land Survey	T <u>3N</u> R <u>5W B-9</u> TR TR	
Property Controlling in Section Miscellaneous Property in Sec.	STR	LIBER 3 PAGE 639 Register of Deeds Stamp & File Number
I, Maurice H. Mahieu, in a fle 74, Michigan P.A. of 1970, th regulations and rules therefore Department of the Interior, Bu corner points mentioned in lines Land Surveyors or by a Decree recovered, found as expressed	eld survey on June 15, 1995 do hereby certify that under requirements of P te corner points mentioned in lines 1 and 2 above were in conformance were as required in the current manual of survey instructions of the United Statureau of Land Management or by a decree of a Court of Law and /or that it is 3, 4 and 5 above were in conformance with the rules of the Michigan Board to of a Court of Law; established, re-established, monumented, re-monumented below:	tes 5
A. Description of original in Original GLO survey 19 1827 "Set 1/4 sec po	nonument and accessories and/or subsequent restoration: done by Orange Risdon, U.S. Deputy Surveyor on March	11 12 -31 -32 -33 -34 -35 -36

- 2. On December 12, 1875, Oscar G. Church, County Surveyor, recorded corner as "stone" (Volume 1, Pages 246-247 of County Surveyor Records)
- 3. On February 26, 1876, Oscar G. Church, County Surveyor, recorded corner as "stake" (Volume 2, Pages 6-7 of County Surveyor Records)
- 4. Eaton County Road Commission record witnesses as:

9" Beech SE 3 8" Beech NW 32

Beech 9 567E 3 Do 8 N63W 32"

(CONTINUED ON BACK)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" x 18" iron rerod in monument box 0.6' =/- south of centerline of Vermontville Highway. Found two witnesses recorded to Kay Don Fluke PS #18988 in Liber 1, Page 250 on Sept. 25, 1972. Found no evidence of nail and tag in witness trees. Measured N49°E, 56.6' +/- to centerline of 36" Maple and measured N41°W 49.5'+/- to centerline of 36" Maple. Excavated 2' diameter hole a depth of 2.5', and found no evidence. Accepted 1/2" rebar for corner and replaced with standard 3/4" x 24" smooth iron rod and cap stamped "PA 345 PS #28414. This surveyor accepts the location of the 1/2" iron rerod and the best location for the perpetuation of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" x 24" iron rod with cap "P.A. 345 #28414" witnessed by:

Nail & Tag #28414 in east side 36* Maple, N41°W, 48.30 feet

Nail & Tag #28414 in west side 36" Maple, N49" E, 55.85 feet

Nail & Tag #28414 in northwest side 38" Maple N70°E, 113.15 feet

Nail & Tag #28414 in north side Twin Ash S79°E, 104.42 feet

Surveyor's Michigan License No. 28414

MAURICE H MAHIEU SURVEYOR NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1 REVISED MAY 14,1

(PART A CONTINUED)

5. Kay Don Fluke PS # 18988 in an Act 132 survey recorded in Liber , Pages 279-280 called for a ½" rod with RLS cap #18988 witnessed by:

N30W-48.85-Maple 32"

N10W-40.24 Maple 20"

N45E -56.40-Maple 25"

S40E -63.25-Beech 4"

Survey was dated September 25, 1972

- 6. Corner recorded and remonumented by Kay Don Fluke PS #18988 in September 25, 1972 Act 74 corner remonumentation (L-1, P-250). Set ½" rod with RLS cap #18988 by proportionate of measured as to recorded (Measured 5771.03) (Recorded 5773.68) along N section line with some witnesses as A-5.
- 7. Corner recorded by Herbert L. Fluharty PS #18223 in October 5, 1980, ACT 74 corner recordation (L-2, P-684).

FD. 1/2" iron, on E-W centerline road.

Witnessed by:

8" Beech S58°E 63.34

26" Maple N54°E 56.43

32" Maple N40°W 48.89

8. James E Stephens PS #16053 in an Act 132 Survey recorded in Liber 3, Page 505 called for a ½" rod and cap #18988 witnessed by:

32" Maple N30°W 48.85 feet

20" Stump N10°W 40.24 feet

25" Maple N45 E 56.40 feet

8" Beech S40°E 63.40 feet

Survey was dated March 17, 1983

- 9. Robert G. Reed PS #19004 in an Act 132 Survey recorded in Liber 3, Pages 948-949 called for a ½" rod with cap with same witnesses as A-5 survey was dated November 16, 1985.
- 10. Douglas K. Richardson PS #31603 in an Act 132 Survey recorded in Liber 4, Pages 729-730 dated May 5th 1989 called for the same corner and witnesses as recorded in Liber 2, Page 684.
- 11. Douglas K. Richardson PS #31603 in an Act 132 Survey recorded in Liber 4, Page 722 dated June 5, 1989 called for the same corner and witnesses as recorded in Liber 2, Page 684.
- 12. Larry A. Bryan PS #25832 in an Act 132 Survey recorded in Liber 4, Pages 803-804 dated December 18, 1989 called for a 1/2" bar in center line of Vermontville Highway, witnessed by:

Found Nail & Tag, southwest side 32" Maple, N30°W, 48.90 feet

Found Nail & Tag, west side 20" Stump, N10°W, 40.10 feet

Found Nail & Tag, southeast side 24" Maple, N45°E, 56.40 feet

Found Nail & Tag, northeast side 12" Maple, 540°E, 63.32 feet

13. Jerry D. Taylor LS #32342 in an Act 132 Survey recorded in Liber 5, Page 532 dated December 26, 1992 called for a ½" iron rod witnessed by:

8" Ash S58"E, 63.34 feet

26" Maple N54°E, 56.43 feet

32" Maple N40°W, 48.83 feet

