CONTRACTOR

95 NOV 28 PM 2: 03

	LAND CORNER RECORDATION CERTIFICA Filing Requirement of Act 74, Mich. P.A. 19	170
For corners in	Located In: CHESTER TOWNSHIP Corner Code #	LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY. MICH.
1. Public Land Survey	T <u>3N</u> R <u>5W D-7</u> T R T R T R	
Property Controlling in Section Miscellaneous Property in Sec.	S TR	LIBER 3 THE 6.11 Register of Deeds Stamp & File Number
	rded Plat	A B C D E F G H I J K L 2 6 5 4 3 2 1
74. Michigan P.A. of 1970, the regulations and rules therefore. Department of the Interior, Burnary spirits montioned in lines.	If survey on June 28, 1995 do hereby certify that under requirements of P.A. corner points mentioned in lines 1 and 2 above were in conformance with as required in the current manual of survey instructions of the United States eau of Land Management or by a decree of a Court of Law and for that the 3, 4 and 5 above were in conformance with the rules of the Michigan Board of a Court of Law; established, re-established, monumented, re-monumented, elow:	4
NOTE: Not more that 4 co on this certificate.	rmers, all in the same town and range, may be recorded	9
A. Description of original me 1. Original GLO corner w 19, 1827 "Set 1/4 sec. pos Sugar 16 S30E Elm 12 N52W	19	12 -31 -32 -33 -34 -35 -36
2. On March 1, 1877, O.0 Pages 42 & 43 County Su	G. Church, Eaton County Surveyor, recorded corner as "Stak urveyor's Records.	e & stone and crockery FOS" in Book 2,
3. Eaton County Road C	ommission grid map has witnesses of: 16" Maple SE 19; 12"	Elm NW 7
4. Act 132 Survey record "Found 1/2" Iron Bar, Witne	led in Liber 1, Page 702, on Aug. 27, 1974 by Sydney G. Bok essed by: 12" Box Elder, SW, 72.79' 9" Box Elder, SW, 92.43' 30" Pine, SW, 112.00'	ovoy, RLS #19828 as reference to corner as

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found ½" x 18" iron rod 4" below gravel road surface. Iron falls in centerline of Gresham Highway and on a treeline to the South. Found 3 witnesses as noted by Sydney Bokovoy #19828. Measured to nail & tag 18988 East side 20" Butternut S55"W 71.33 feet. Measured to nail and ribbon Northwest side of 30" Pine, S50"W 112.11 feet. Also found PK nail in Northwest side of same 30" pine and measured 111.79 feet. Measured to nail and tag #18988 northwest side of 20" butternut S40°W 92.47 feet. Excavated 3' x 4' hole at an average depth of 18". Found broken 6 sided clay tile surrounded by smaller rocks which were surrounded by larger rocks. The ½" rods falls north 0.50' and West 1.60 feet of clay tile. This surveyor feels that the tile is the best perpetuated location of the corner because of the county surveyors records. Removed the tile and set a standard 3/4" x 24" smooth iron rod with cap stamped "P.A. 345 P.S. 28414" in location of broken clay tile.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 3/4" x 24" smooth iron rod with cap stamped "P.A. 345 P.S. 28414" witnessed by: Nail and tag #28414 Northwest side of 30" Pine, S52°W, 113.07 feet Nail and tag #28414 North side 24" Walnut, S71°W, 165.56 feet

Nail and tag #18998 Northwest side of 20" Butternut, S41°W, 93.15 feet

Nail and tag #28414 East side 20" Butternut, S56°W, 72.37 feet

Centerline of top of Telephone cable box, N43°E, 43.38 feet

Journal Signed by _ Surveyor's Michigan License No. 28414

