

MAY 0 5 1997

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MILHIGAN EMMET COUNTY RECORDED	í
urcaknen	

96 DEC 31 PM 2: 25

Glenna a Signer

LIBER A

Register of Deeds Stamp & File Number

EMMET (County)	Located In:	Corner Code # TOWNSHIP
1. Public Länd Survey	T <u>34</u> R <u>5 W</u> T R	C-2
ECRP#18	TR TR	
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R	

____, Recorded Plat 5. Private Claims

I, <u>Richard E Oelke</u>, in a field survey on <u>20 December</u>, 19 <u>96</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate.

4 5 6

A. Description of original monument and accessories and/or subsequent restoration: C-2.....1/4 corner common to Sections 5, 6,, T34N, R5W See Outline of Corner History on back.

This corner was used extensively at the turn of the century. It was probably lost when Howard Rd. was upgraded and a sewer was added... Howard road was rebuild in 1995 and a thourgh search was make afer road surface had been APPROVED LAND CORNER removed... nothing was found of original corner.

P.A. 345 OF 1990 **Emmet County** GENLE 12.30.96

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-2.....1/4 corner common to Sections 5, 6, T34N, R5W

Found post at SW cor. of Bumps Lot, (witness to corner from city of Petoskey corner witness book) measured 33.3 feet from outside edge (E face) to determine Easting of corner. Used centerline of West Rush Street extended to determine Northing of corner. This point matchs well with the North line of East Rush St... and is harmoniously related to the plats in the area.

WITNESSED AS FOLLOWS:

N90°E

33.3' east edge of SW concrete post Bumps Lot

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-2......1/4 corner common to Sections 5, 6, T34N, R5W

Replaced 3/4" iron star drill with a 2" diameter, 30" long PVC pipe, with a base magnet and a standard Emmet County Survey Remonumentation Program cap. This position is accepted as a careful and faithful perpetuation of the original corner. **OELKE** PROFESSIONAL

NEW WITNESSES:

N11°E	125.03	p.p., nail capp	ped PS# 33983 in E face
S78°E	24.82	p.p., nail capp	bed PS# 33983 in S face
S65°W	58.45	20" maple.	nail capped PS# 33983 in N face

20" maple., S65°W nail canned PS# 33983 in NW face

N79°W	83.45' p.p., nail capped P5# 33963 in NW lac	æ	0153310
Signed by	R.E. OFWE	Date20 December	·
-	Michigan License No. 33983	April American Company of the Compan	

SURVEYOR No. 33983

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 125

PAGE 114

34-5-C2 1/4 Corner between Sections 5 & 6, T34N, R5W Howard Street/Rush Street

Date	Surveyor	Found	Witnesses	<u>Notes</u>
1840	Gro	Set 1/4 Section post.		26L 6" Beech 30L 6" Beech
1885	Keep	Restablished corner f with a cross and char	rom existing be	aring tree, placed large stone ow surface.
1900	Keep	Ran E-W 1/4 line of S	ec. 5, Fd. corn	er
1902	Keep		and wooden stak E. 33.3'	e in cross 14" below surface. outside post at SW Bumps Lot